



Automotive Safety Council

Prevent

Protect

Notify

NHTSA Recalls of Interest

April 22, 2024

Unintended Acceleration from Trapped Pedal

A trapped accelerator pedal can cause the vehicle to accelerate unintentionally, increasing the risk of a crash.

NHTSA Campaign Number: 24V276000

Manufacturer Tesla, Inc.

Components VEHICLE SPEED CONTROL

Potential Number of Units Affected 3,878

Summary

Tesla, Inc. (Tesla) is recalling certain 2024 Cybertruck vehicles. The accelerator pedal pad may dislodge and cause the pedal to become trapped by the interior trim.

Remedy

Tesla service will replace or repair the accelerator pedal assembly, free of charge. Owner notification letters are expected to be mailed in June 2024. Owners may contact Tesla customer service at 1-877-798-3752. Tesla's number for this recall is SB-24-33-003.

Vehicle

MAKE	MODEL	YEAR
TESLA	CYBERTRUCK	2024

Front Air Bag May Not Deploy Properly/FMVSS 208

Incorrect detection of an occupant may result in improper air bag deployment during a crash, increasing the risk of injury.

NHTSA Campaign Number: 24V275000

Manufacturer Toyota Motor Engineering & Manufacturing

Components AIR BAGS

Potential Number of Units Affected 509

Summary

Toyota Motor Engineering & Manufacturing (Toyota) is recalling certain 2018-2021 Lexus LS500 and 2018-2020 Lexus LS500 Hybrid vehicles equipped with the "Executive Package." The front passenger seat may have been assembled with interference between internal parts that can cause the Occupant Classification System (OCS) sensor to incorrectly detect the occupant. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 208, "Occupant Crash Protection."

Remedy

Dealers will inspect and repair the front passenger seat, as necessary, free of charge. Owner notification letters are expected to be mailed June 2, 2024. Owners may contact Toyota customer service at 1-800-331-4331. Toyota's number for this recall is 24LA03.

Vehicles

MAKE	MODEL	YEAR
LEXUS	LS	2018-2021
LEXUS	LS HYBRID	2018-2020

Unlocked Rear Door May Open Unexpectedly

A door that unexpectedly opens while the vehicle is moving or during a crash increases the risk of injury.

NHTSA Campaign Number: 24V274000

Manufacturer Toyota Motor Engineering & Manufacturing

Components ELECTRICAL SYSTEM, LATCHES/LOCKS/LINKAGES

Potential Number of Units Affected 55,690

Summary

Toyota Motor Engineering & Manufacturing (Toyota) is recalling certain 2023-2024 Prius and Prius Prime vehicles. Water may enter the rear door switch and cause a short circuit, allowing an unlocked rear door to open unexpectedly.

Remedy

Dealers will replace both right and left rear door opener switches, free of charge. Owner notification letters are expected to be mailed June 2, 2024. Owners may contact Toyota customer service at 1-800-331-4331. Toyota's numbers for this recall are 24TB06 and 24TA06.

Vehicles

MAKE	MODEL	YEAR
TOYOTA	PRIUS	2023-2024
TOYOTA	PRIUS PRIME	2023-2024
