



Automotive Safety Council

Prevent

Protect

Notify

NHTSA Recalls of Interest

April 29, 2024

Rearview Camera Image May Not Display/FMVSS 111

A rearview camera image that does not display decreases the driver's visibility, increasing the risk of injury or crash.

NHTSA Campaign Number: 24V289000

Manufacturer Chrysler (FCA US, LLC)

Components BACK OVER PREVENTION

Potential Number of Units Affected 8

Summary

Chrysler (FCA US, LLC) is recalling certain 2022-2023 Jeep Grand Cherokee and 2023-2024 Jeep Grand Cherokee L vehicles. An improperly connected coaxial cable may prevent the rearview camera image from displaying. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 111, "Rear Visibility."

Remedy

Dealers will secure the coaxial cable connection, free of charge. All affected vehicles have been remedied. Owners may contact FCA US, LLC customer service at 1-800-853-1403. FCA US, LLC's number for this recall is 40B.

Vehicle

MAKE	MODEL	YEAR
JEEP	GRAND CHEROKEE	2022-2024

Rearview Camera Image May Not Display/FMVSS 111

A rearview camera image that does not display decreases the driver's visibility, increasing the risk of injury or crash.

NHTSA Campaign Number: 24V291000

Manufacturer Chrysler (FCA US, LLC)

Components BACK OVER PREVENTION

Potential Number of Units Affected 2

Summary

Chrysler (FCA US, LLC) is recalling certain 2023 Jeep Grand Cherokee and Grand Cherokee L vehicles. Improperly fastened screen module connections may prevent the rearview camera image from displaying. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 111, "Rear Visibility."

Remedy

Dealers will secure the display screen module connections, free of charge. All vehicles have been remedied. Owners may contact FCA US, LLC customer service at 1-800-853-1403. FCA US, LLC's number for this recall is 44B.

Vehicle

MAKE	MODEL	YEAR
JEEP	GRAND CHEROKEE	2023

Inoperative Electronic Stability Control/FMVSS 126

Driving with an inoperative electronic stability control system can increase the risk of a crash.

NHTSA Campaign Number: 24V290000

Manufacturer Chrysler (FCA US, LLC)

Components ELECTRONIC STABILITY CONTROL (ESC)

Potential Number of Units Affected 2

Summary

Chrysler (FCA US, LLC) is recalling certain 2021 Ram Promaster vehicles. An insecure ground connection may cause the electronic stability control (ESC) to be inoperative. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 126, "Electronic Stability Control Systems."

Remedy

Dealers will tighten the ground nut assembly, free of charge. All affected vehicles have been remedied. Owners may contact FCA US, LLC customer service at 1-800-853-1403. FCA US, LLC's number for this recall is 43B.

Vehicle

MAKE	MODEL	YEAR
RAM	PROMASTER	2021

Air Bag Inflators May Rupture

An inflator that ruptures may cause sharp metal fragments to enter or exit the vehicle, increasing the risk of injury. Additionally, an inflator that leaks gas may only partially inflate during a crash, increasing the risk of injury.

NHTSA Campaign Number: 24V288000

Manufacturer BMW of North America, LLC

Components AIR BAGS

Potential Number of Units Affected 5,761

Summary

BMW of North America, LLC (BMW) is recalling certain 2014-2015 2 Series Coupe (228i, 228i xDrive, M235i), 3 Series Sedan (320i, 320i xDrive, 328i, 328i xDrive, 335i, 335i xDrive, M3, 328d, 328d xDrive), 4 Series Coupe (428i, 428i xDrive, 435i, 435i xDrive, M4), and 2015 4 Series Gran Coupe (428i, 428i xDrive, 435i, 435i xDrive) vehicles. The head air bag inflator may fail at the weld joint, which can cause gas to leak from the inflator or result in an inflator rupture.

Remedy

Dealers will replace the head air bags, free of charge. Owner notification letters are expected to be mailed June 14, 2024. Owners may contact BMW customer service at 1-800-525-7417.

Vehicles

MAKE	MODEL	YEAR
BMW	228I	2014-2015

BMW	320I	2014-2015
-----	------	-----------

MAKE	MODEL	YEAR
BMW	328D	2014-2015
BMW	328I	2014-2015
BMW	335I	2014-2015
BMW	428I	2014-2015
BMW	435I	2014-2015
BMW	M235I	2014-2015
BMW	M3	2014-2015
BMW	M4	2014-2015

Driver's Side Air Bag May Deploy Improperly

Without a deflector, the air bag may deploy improperly, increasing the risk of injury during a crash.

NHTSA Campaign Number: 24V284000

Manufacturer Tesla, Inc.

Components AIR BAGS

Potential Number of Units Affected 1

Summary

Tesla, Inc. (Tesla) is recalling one 2024 Model 3 vehicle. The driver seat side air bag module was assembled without a deflector that directs gas flow during deployment.

Remedy

Tesla service replaced the side air bag, free of charge. The affected vehicle was repaired April 12, 2024. Owners may contact Tesla customer service at 1-877-798-3752. Tesla's number for this recall is SB-24-13-001.

Vehicle

MAKE	MODEL	YEAR
TESLA	MODEL 3	2024

Passenger Air Bag May Tear

A torn air bag may not adequately protect an occupant in a crash, increasing the risk of injury. Additionally, a torn air bag may allow the escape of hot gases which can burn an occupant.

NHTSA Campaign Number: 24V278000

Manufacturer Jaguar Land Rover North America, LLC

Components AIR BAGS

Potential Number of Units Affected 2,409

Summary

Jaguar Land Rover North America, LLC (Jaguar) is recalling certain 2021-2023 E-Pace vehicles. The passenger air bag may tear during deployment.

Remedy

Dealers will replace the passenger air bag module, free of charge. Owner notification letters are expected to be mailed June 14, 2024. Owners may contact Jaguar customer service at 1-800-452-4827. Jaguar's number for this recall is H491.

Vehicle

MAKE	MODEL	YEAR
JAGUAR	E-PACE	2021-2023

Loss of Power Steering Assist

A loss of power steering assist increases the risk of a crash.

NHTSA Campaign Number: 24V287000

Manufacturer Kia America, Inc.

Components ELECTRICAL SYSTEM

Potential Number of Units Affected 95

Summary

Kia America, Inc. (Kia) is recalling certain 2024 Sorento vehicles. The motor driven power steering (MDPS) wiring harness may be incorrectly assembled, which can result in a loss of power steering assist.

Remedy

Dealers will inspect and repair, or replace the MDPS wiring harness as necessary, free of charge. Owner notification letters are expected to be mailed May 7, 2024. Kia's number for this recall is SC309.

Vehicle

MAKE	MODEL	YEAR
KIA	SORENTO	2024

Loss of Drive Power from Fuel Pump Failure

A loss of drive power can increase the risk of a crash.

NHTSA Campaign Number: 24V282000

Manufacturer Hyundai Motor America

Components FUEL SYSTEM, GASOLINE

Potential Number of Units Affected 31,440

Summary

Hyundai Motor America (Hyundai) is recalling certain 2022-2023 Genesis GV70, GV80, G80, and G90 vehicles. The fuel pump may fail, which can result in a loss of drive power.

Remedy

Dealers will inspect and replace the fuel pump assembly, free of charge. Owner notification letters are expected to be mailed June 18, 2024. Owners may contact Hyundai customer service at 1-855-371-9460. Hyundai's number for this recall is 022G. This recall is an expansion of recall number 23V-630.

Vehicles

MAKE	MODEL	YEAR
GENESIS	G80	2022-2023
GENESIS	G90	2022-2023

MAKE

MODEL

YEAR

GENESIS

GV70

2022-2023

GENESIS

GV80

2022-2023
