



Automotive Safety Council

Prevent

Protect

Notify

NHTSA Recalls of Interest

June 3, 2024

Rearview Camera Image May Not Display Properly

A flickering or distorted rearview camera image can reduce the driver's rear visibility, increasing the risk of a crash.

NHTSA Campaign Number: 24V368000

Manufacturer Ford Motor Company

Components BACK OVER PREVENTION

Potential Number of Units Affected 109,283

Summary

Ford Motor Company (Ford) is recalling certain 2020-2024 Lincoln Aviator vehicles. The accessory protocol image module (APIM) can be affected by electromagnetic interference with a cell phone in the vehicle, causing the rearview camera image to flicker or become distorted.

Remedy

Owners are advised not to use their cell phones while reversing until the remedy is completed. Dealers will install shielding on the accessory protocol image module (APIM), free of charge. Owner notification letters are expected to be mailed July 8, 2024. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 24S35.

Vehicle

MAKE	MODEL	YEAR
LINCOLN	AVIATOR	2020-2024

Rearview Camera Image May Not Display/FMVSS 111

A rearview camera image that does not display can decrease the driver's visibility, increasing the risk of injury or crash.

NHTSA Campaign Number: 24V364000

Manufacturer Jaguar Land Rover North America, LLC

Components BACK OVER PREVENTION

Potential Number of Units Affected 22,268

Summary

Jaguar Land Rover North America, LLC (Land Rover) is recalling certain 2018-2022 Range Rover Sport vehicles equipped with a Surround Camera System. Water may enter into the rearview camera, which can cause the rearview camera image not to appear on the display or display a distorted image. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 111, "Rear Visibility."

Remedy

Dealers will inspect the rearview camera for damage. If no damage is found, the camera will be fitted with a new seal. If damage is found, the camera will be replaced and calibrated. Repairs will be performed free of charge. Owner notification letters are expected to be mailed July 19, 2024. Owners may contact Land Rover customer service at 1-800-637-6837. Land Rover's number for this recall is N901. These vehicles were previously recalled under 24V-023 for this same issue and will need to have the new remedy completed.

Vehicle

MAKE	MODEL	YEAR
LAND ROVER	RANGE ROVER SPORT	2018-2022

Air Bags May Fail to Deploy

Inactive ignitors can prevent the air bags from deploying, increasing the risk of injury during a crash.

NHTSA Campaign Number: 24V369000

Manufacturer VinFast Auto, LLC

Components AIR BAGS

Potential Number of Units Affected 284

Summary

VinFast Auto, LLC (VinFast) is recalling certain 2022-2024 VF8 vehicles. Inactive ignitors may have been installed in the air bags.

Remedy

VinFast will replace the air bags, free of charge. Owner notification letters are expected to be mailed June 7, 2024. Owners may contact VinFast customer service at 1-833-503-0600. VinFast's number for this recall is VPAC-291.

Vehicle

MAKE	MODEL	YEAR
VINFAST	VF8	2022-2024

Seat Belt Warning System Malfunction/FMVSS 208

A seat belt warning system that fails to alert occupants of an unbelted seat belt can increase the risk of injury during a crash.

NHTSA Campaign Number: 24V376000

Manufacturer Tesla, Inc.

Components SEAT BELTS

Potential Number of Units Affected 125,227

Summary

Tesla, Inc. (Tesla) is recalling certain 2012-2024 Model S, 2015-2024 Model X, 2017-2023 Model 3, and 2020-2023 Model Y vehicles. In the event of an unbelted driver, the seat belt warning light and audible chime may not activate as intended. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 208, "Occupant Crash Protection."

Remedy

Tesla will release an over-the-air (OTA) software update. Owner notification letters are expected to be mailed July 27, 2024. Owners may contact Tesla customer service at 1-877-798-3752. Tesla's number for this recall is SB-24-00-008.

Vehicles

MAKE	MODEL	YEAR
TESLA	MODEL 3	2017-2023
TESLA	MODEL S	2012-2024

MAKE	MODEL	YEAR
TESLA	MODEL X	2015-2024
TESLA	MODEL Y	2020-2023

Seat Wiring Harnesses Incorrectly Routed

A damaged wiring harness can prevent the air bags installed in the seats from deploying as intended during a crash, increasing the risk of injury.

NHTSA Campaign Number: 24V371000

Manufacturer Mercedes-Benz USA, LLC

Components ELECTRICAL SYSTEM, SEATS

Potential Number of Units Affected 18

Summary

Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2023 AMG C43 4MATIC vehicles, equipped with AMG Performance seats. The seat wiring harness may be incorrectly routed, which can cause it to become damaged when the seat is fully reclined.

Remedy

Dealers will inspect and reroute the wiring harness, as necessary, free of charge. Owner notification letters are expected to be mailed July 23, 2024. Owners may contact MBUSA customer service at 1-800-367-6372.

Vehicle

MAKE	MODEL	YEAR
MERCEDES-BENZ	AMG C43	2023

High-Voltage Battery May Shutdown Unexpectedly

A sudden loss of drive power increases the risk of a crash.

NHTSA Campaign Number: 24V372000

Manufacturer Mercedes-Benz USA, LLC

Components ELECTRICAL SYSTEM

Potential Number of Units Affected 14,912

Summary

Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2024 EQE 350 4MATIC, EQE 350+, EQE 500 4MATIC, EQS 450 4MATIC, EQS 450+, EQS 580 4MATIC, AMG EQE 53 4MATIC, AMG EQS 53 4MATIC, 2023-2025 EQE SUV 350 4MATIC, EQE SUV 350+, EQE SUV 500 4MATIC, EQS SUV 450 4MATIC, EQS SUV 450+, EQS SUV 580 4MATIC, 2024-2025 EQS SUV 680 4MATIC, and AMG EQE SUV 53 4MATIC vehicles. The battery management system software may cause the high-voltage battery to shut down, which can result in a sudden loss of drive power.

Remedy

Dealers will update the battery management system software, free of charge. Owner notification letters are expected to be mailed July 23, 2024. Owners may contact MBUSA customer service at 1-800-367-6372.

Vehicles

MAKE	MODEL	YEAR
MERCEDES-BENZ	AMG EQE 53 4MATIC	2024
MERCEDES-BENZ	AMG EQE SUV 53 4MATIC	2024-2025
MERCEDES-BENZ	AMG EQS 53 4MATIC	2024
MERCEDES-BENZ	EQE 350 4MATIC	2024
MERCEDES-BENZ	EQE 350+	2024
MERCEDES-BENZ	EQE 500	2024
MERCEDES-BENZ	EQE SUV 350 4MATIC	2023-2025
MERCEDES-BENZ	EQE SUV 350+	2023-2025
MERCEDES-BENZ	EQE SUV 500 4MATIC	2023-2025

MAKE	MODEL	YEAR
MERCEDES-BENZ	EQS 450	2024
MERCEDES-BENZ	EQS 450+	2024
MERCEDES-BENZ	EQS 580	2024
MERCEDES-BENZ	EQS SUV 450 4MATIC	2023-2025
MERCEDES-BENZ	EQS SUV 450+	2023-2025
MERCEDES-BENZ	EQS SUV 580 4MATIC	2023-2025
MERCEDES-MAYBACH	EQS SUV 680 4MATIC	2024-2025

Incorrect Headlight Software/FMVSS 108

Incorrect headlight control module software may cause the parking lights not to operate as intended when the headlights are turned on and the turn signals are activated, which can reduce vehicle visibility and increase the risk of a crash.

NHTSA Campaign Number: 24V361000

Manufacturer Volkswagen Group of America, Inc.

Components EXTERIOR LIGHTING

Potential Number of Units Affected 17,797

Summary

Volkswagen Group of America, Inc. (Audi) is recalling certain 2022-2024 Q4 E-TRON and Q4 E-TRON Sportback vehicles. The incorrect headlight control module software may have been installed. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 108, "Lamps, Reflective Devices, and Associated Equipment."

Remedy

Dealers will update the headlight control module with a new data set, free of charge. Owner notification letters are expected to be mailed July 12, 2024. Owners may contact Audi customer service at 1-800-253-2834. Audi's number for this recall is 941L.

Vehicle

MAKE

MODEL

YEAR

AUDI

Q4 E-TRON

2022-2024
