



# Automotive Safety Council

Prevent

Protect

Notify

## NHTSA Recalls of Interest

June 10, 2024

### Disabled Electronic Stability Control/FMVSS 126

Driving with a disabled electronic stability control system can increase the risk of a crash.

**NHTSA Campaign Number:** 24V415000

**Manufacturer** Chrysler (FCA US, LLC)

**Components** ELECTRONIC STABILITY CONTROL (ESC), SERVICE BRAKES, AIR

**Potential Number of Units Affected** 211,581

#### Summary

Chrysler (FCA US, LLC) is recalling certain 2022 Dodge Durango and Ram 2500 and 3500 vehicles. Due to a software malfunction, the ABS control module may disable the electronic stability control system. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 126, "Electronic Stability Control Systems."

#### Remedy

Dealers will update the ABS control module software, free of charge. Owner notification letters are expecting to be mailed July 26, 2024. Owners may contact FCA US, LLC customer service at 1-800-853-1403. FCA US, LLC's number for this recall is 55B.

#### Vehicles

---

MAKE	MODEL	YEAR
DODGE	DURANGO	2022

---

---

MAKE	MODEL	YEAR
RAM	2500	2022
RAM	3500	2022

---

## Fire from Overheated Power Seat Motor

A fire increases the risk of injury.

**NHTSA Campaign Number:** 24V407000

**Manufacturer** Kia America, Inc.

**Components** SEATS

**Potential Number of Units Affected** 462,869

### Summary

Kia America, Inc. (Kia) is recalling certain 2020-2024 Telluride vehicles. The front power seat motor may overheat due to a stuck power seat slide knob, which can result in a fire while parked or driving.

### Remedy

Owners are advised to park outside and away from structures until the recall repair is complete. Dealers will install a bracket for the power seat switch back covers and replace the seat slide knobs, free of charge. Owner notification letters are expected to be mailed July 30, 2024. Owners may contact Kia customer service at 1-800-333-4542. Kia's number for this recall is SC316.

### Vehicle

---

MAKE	MODEL	YEAR
KIA	TELLURIDE	2020-2024

---

## Transmission May Shift Into Neutral While Driving

A loss of drive power can increase the risk of a crash.

**NHTSA Campaign Number:** 24V380000

**Manufacturer** Jaguar Land Rover North America, LLC

## Components POWER TRAIN

**Potential Number of Units Affected** 19

### Summary

Jaguar Land Rover North America, LLC (Land Rover) is recalling certain 2024 Range Rover and Range Rover Sport vehicles. The transmission oil pressure may decrease and cause the clutch to shift into neutral gear, which can result in a loss of drive power.

### Remedy

Dealers will inspect and replace the transmission as necessary, free of charge. Owner notification letters are expected to be mailed July 26, 2024. Owners may contact Land Rover customer service at 1-800-637-6837. Land Rover's number for this recall is N903.

### Vehicles

MAKE	MODEL	YEAR
LAND ROVER	RANGE ROVER	2024
LAND ROVER	RANGE ROVER SPORT	2024

## Inoperative Rearview Camera Display/FMVSS 111

An inoperative rearview camera display can reduce the driver's rear visibility, increasing the risk of a crash.

**NHTSA Campaign Number:** 24V384000

**Manufacturer** Honda (American Honda Motor Co.)

**Components** BACK OVER PREVENTION

**Potential Number of Units Affected** 114,686

### Summary

Honda (America Honda Motor Co.) is recalling certain 2018-2020 Fit and 2019-2022 HR-V vehicles that were previously recalled under NHTSA recall number 23V-046. The rearview camera image may not display when the engine is started with a key, due to a design error in the audio display power circuit. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 111, "Rear Visibility."

### Remedy

Dealers will update the display audio unit software, free of charge. Owner notification letters are expected to be mailed July 8, 2024. Owners may contact Honda service at 1-888-234-2138. Honda's numbers for this recall are TIQ and DIR. Vehicles previously repaired under recall 23V-046 will need to have the new remedy completed.

## Vehicles

---

MAKE	MODEL	YEAR
HONDA	FIT	2018-2020
HONDA	HR-V	2019-2022

## Loss of Steering from Tie Rod Separation

Tie rod separation can cause a sudden loss of steering control and increase the risk of a crash.

**NHTSA Campaign Number:** 24V402000

**Manufacturer** Daimler Trucks North America, LLC

**Components** STEERING

**Potential Number of Units Affected** 540

### Summary

Daimler Trucks North America, LLC (DTNA) is recalling certain 2025 Freightliner Cascadia, 108SD, 114SD, Business Class M2, Western Star 47X, 49X, Freightliner Custom Chassis S2RV 106, and S2C 106 transit buses, cabs, and chassis. The front axle tie rod ball joint studs may crack and break, which can result in tie rod separation.

### Remedy

The remedy is currently under development. Owner notification letters are expected to be mailed August 3, 2024. Owners may contact DTNA customer service at 800-745-8000. DTNA's number for this recall is D24R6.

## Vehicles

---

MAKE	MODEL	YEAR
FCCC	S2C	2025
FCCC	S2RV	2025
FREIGHTLINER	108SD	2025

MAKE	MODEL	YEAR
FREIGHTLINER	114SD	2025
FREIGHTLINER	BUSINESS CLASS M2	2025
FREIGHTLINER	CASCADIA	2025
WESTERN STAR	47X	2025
WESTERN STAR	49X	2025

### Loss of Steering from Tie Rod Separation

Tie rod separation can cause a sudden loss of steering control and increase the risk of a crash.

**NHTSA Campaign Number:** 24V401000

**Manufacturer** Daimler Trucks North America, LLC

**Components** STEERING

**Potential Number of Units Affected** 25

**Summary**

Daimler Trucks North America, LLC (DTNA) is recalling certain 2024-2025 Thomas Built Buses Saf-T-Liner C2 school buses. The front axle tie rod ball joint studs may crack and break, which can result in tie rod separation.

**Remedy**

The remedy is currently under development. Owner notification letters are expected to be mailed August 3, 2024. Owners may contact DTNA customer service at 800-745-8000. DTNA's number for this recall is D24R6.

**Vehicle**

MAKE	MODEL	YEAR
THOMAS BUILT BUSES	SAF-T-LINER C2	2024-2025

## Debris in Engine May Cause Stall

A loss of drive power increases the risk of a crash.

**NHTSA Campaign Number:** 24V381000

**Manufacturer** Toyota Motor Engineering & Manufacturing

**Components** ENGINE AND ENGINE COOLING

**Potential Number of Units Affected** 102,092

### Summary

Toyota Motor Engineering & Manufacturing (Toyota) is recalling certain 2022-2023 Tundra and Lexus LX600 vehicles equipped with a V35A engine. Debris from the manufacturing process may contaminate the engine and cause the main bearings to fail, which can result in an engine stall and loss of drive power.

### Remedy

The remedy is currently under development. Interim letters notifying owners of the safety risk are expected to be mailed July 15, 2024. A second notice will be sent once the remedy is available. Owners may contact Toyota customer service at 1-800-331-4331. Toyota's numbers for this recall are 24TB07/24TA07 and 24LB04/24LA04.

### Vehicles

MAKE	MODEL	YEAR
LEXUS	LX	2022-2023
TOYOTA	TUNDRA	2022-2023

## Inadequate Headliner Impact Protection/FMVSS 201

A headliner with inadequate impact protection increases the risk of injury during a crash.

**NHTSA Campaign Number:** 24V400000

**Manufacturer** Kia America, Inc.

**Components** STRUCTURE

**Potential Number of Units Affected** 2,401

### Summary

Kia America, Inc. (Kia) is recalling certain 2024 EV9 vehicles. The headliner may not adequately protect passengers from impact in a crash. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 201, "Occupant Protection In Interior Impact."

## Remedy

Dealers will replace the impact absorbing plates mounted on the headliner, free of charge. Owner notification letters are expected to be mailed July 31, 2024. Owners may contact Kia customer service at 1-800-333-4542. Kia's number for this recall is SC317.

## Vehicle

---

MAKE	MODEL	YEAR
KIA	EV9	2024

---

## Loss of Steering Control

A sudden loss of steering control increases the risk of a crash.

**NHTSA Campaign Number:** 24V396000

**Manufacturer** Volvo Trucks North America

**Components** STEERING

**Potential Number of Units Affected** 488

### Summary

Volvo Trucks North America (Volvo Trucks) is recalling certain 2025 VN, VNRe, and VHD trucks. The drag link may contain an improperly heat-treated ball stud that can fail, resulting in a sudden loss of steering control.

### Remedy

Owners are advised not to drive their vehicle until the repair has been performed. Dealers will inspect and replace the drag links, as necessary, free of charge. Owner notification letters are expected to be mailed August 2, 2024. Owners may contact Volvo Trucks customer service at 1-800-528-6586. Volvo Truck's number for this recall is RVXX2402.

## Vehicles

---

MAKE	MODEL	YEAR
VOLVO	VHD	2025
VOLVO	VN	2025
VOLVO	VNRE (ELECTRIC)	2025

---

## Loss of Steering Control

A sudden loss of steering control increases the risk of a crash.

**NHTSA Campaign Number:** 24V398000

**Manufacturer** Mack Trucks, Inc.

**Components** STEERING

**Potential Number of Units Affected** 790

### Summary

Mack Trucks, Inc. (Mack) is recalling certain 2025 Mack AN, GR, and TE trucks. The drag link may contain an improperly heat-treated ball stud that can fail, resulting in a sudden loss of steering control.

### Remedy

Owners are advised not to drive their vehicles until the remedy has been completed. Dealers will inspect and replace the drag links, as necessary, free of charge. Owner notification letters are expected to be mailed August 2, 2024. Owners may contact Mack customer service at 1-800-866-1177. Mack's number for this recall is SC0465.

### Vehicles

MAKE	MODEL	YEAR
MACK	ANTHEM (AN)	2025
MACK	GRANITE (GR)	2025
MACK	TE	2025

## Loss of Steering and Drive Power

A sudden loss of steering control and drive power increases the risk of a crash.

**NHTSA Campaign Number:** 24V399000

**Manufacturer** Mack Trucks, Inc.

**Components** ELECTRICAL SYSTEM

**Potential Number of Units Affected** 24

### Summary



Mack Trucks, Inc. (Mack) is recalling certain 2024 MMDe electric trucks. The battery management system software may cause the high-voltage battery to shut down, which can result in a sudden loss of steering control and drive power.

**Remedy**

Owners are advised not to drive their vehicles until the remedy has been completed. Dealers will update the battery management system software, free of charge. Owner notification letters are expected to be mailed August 2, 2024. Owners may contact Mack customer service at 1-800-866-1177. Mack's number for this recall is SC0464.

**Vehicle**

---

MAKE	MODEL	YEAR
MACK	MD (ELECTRIC)	2024

---

**Sudden Loss of Power Steering Assist**

A sudden loss of power steering assist increases the risk of a crash.

**NHTSA Campaign Number:** 24V397000

**Manufacturer** Volvo Trucks North America

**Components** STEERING

**Potential Number of Units Affected** 424

**Summary**

Volvo Trucks North America (Volvo Trucks) is recalling certain 2025 VN and VHD trucks. The steering gear may have an improperly seated plug in the valve housing, which can result in a sudden loss of steering control.

**Remedy**

Dealers will inspect the plug and replace the steering gear as necessary, free of charge. Owner notification letters are expected to be mailed August 2, 2024. Owners may contact Volvo Trucks customer service at 1-800-528-6586. Volvo Truck's number for this recall is RVXX2403.

**Vehicles**

---

MAKE	MODEL	YEAR
VOLVO	VHD	2025
VOLVO	VN	2025

---

# Unexpected Loss of Drive Power

An unexpected loss of drive power increases the risk of a crash.

**NHTSA Campaign Number:** 24V391000

**Manufacturer** Nissan North America, Inc.

**Components** ELECTRICAL SYSTEM

**Potential Number of Units Affected** 84

## Summary

Nissan North America, Inc. (Nissan) is recalling certain 2023 Ariya vehicles. O-rings inside the electric front traction motor may have been damaged during assembly, which can result in an internal oil leak and an unexpected loss of drive power.

## Remedy

Dealers will replace the front traction motor assembly, free of charge. Owner notification letters are expected to be mailed July 12, 2024. Owners may contact Nissan's customer service at 1-800-867-7669. Nissan's number for this recall is R24A3C.

## Vehicle

---

MAKE	MODEL	YEAR
NISSAN	ARIYA	2023

---