



Automotive Safety Council

Prevent

Protect

Notify

NHTSA Recalls of Interest

October 28, 2024

Front Passenger Air Bag Fabric May Be Damaged

A damaged air bag may not inflate properly, increasing the risk of injury in a crash.

NHTSA Campaign Number: 24V772000

Manufacturer BMW of North America, LLC

Components AIR BAGS

Potential Number of Units Affected 7

Summary

BMW of North America, LLC (BMW) is recalling certain 2025 X3 xDrive30i and X3 M50i vehicles. The front passenger air bag fabric may have been damaged during transport between suppliers.

Remedy

Dealers will replace the front passenger air bag, free of charge. None of the affected vehicles have been sold yet and therefore no owner notification letters will be mailed. Owners may contact BMW customer service at 1-800-525-7417.

Vehicle

MAKE	MODEL	YEAR
BMW	X3	2025

High-Pressure Fuel Pump May Leak

A fuel leak in the presence of an ignition source can increase the risk of a fire.

NHTSA Campaign Number: 24V763000

Manufacturer Honda (American Honda Motor Co.)

Components FUEL SYSTEM, GASOLINE

Potential Number of Units Affected 720,810

Summary

Honda (American Honda Motor Co.) is recalling certain 2023-2024 Honda Accord, Accord Hybrid, 2023-2025 Honda CR-V Hybrid, and 2025 Honda Civic and Civic Hybrid vehicles. The high-pressure fuel pump may crack and leak fuel.

Remedy

Dealers will inspect and replace the high-pressure fuel pump as necessary, free of charge. Owner notification letters are expected to be mailed December 4, 2024. Owners may contact Honda customer service at 1-888-234-2138. Honda's number for this recall is PJW.

Vehicles

MAKE	MODEL	YEAR
HONDA	ACCORD	2023-2024
HONDA	ACCORD HYBRID	2023-2024
HONDA	CIVIC	2025
HONDA	CIVIC HYBRID	2025
HONDA	CR-V HYBRID	2023-2025

Damaged Tire Sidewall

A sudden loss of tire pressure can result in a loss of vehicle control, increasing the risk of a crash.

NHTSA Campaign Number: 24V767000

Manufacturer Toyota Motor Engineering & Manufacturing

Components TIRES

Potential Number of Units Affected 11,890

Summary

Toyota Motor Engineering & Manufacturing (Toyota) is recalling certain 2024 Sequoia Hybrid, Tundra and Tundra Hybrid vehicles. The passenger-side front and rear tires may have inner sidewall damage, which can cause a sudden loss of tire pressure.

Remedy

Dealers will inspect and replace the tires as necessary, free of charge. Owner notification letters are expected to be mailed November 30, 2024. Owners may contact Toyota customer service at 1-800-331-4331. Toyota's number for this recall is 24TA12.

Vehicles

MAKE	MODEL	YEAR
TOYOTA	SEQUOIA HYBRID	2024
TOYOTA	TUNDRA	2024
TOYOTA	TUNDRA HYBRID	2024

Damaged Tire Sidewall

A sudden loss of tire pressure can result in a loss of vehicle control, increasing the risk of a crash.

NHTSA Campaign Number: 24V780000

Manufacturer Mercedes-Benz USA, LLC

Components TIRES

Potential Number of Units Affected 415

Summary

Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2025 GLB 250, GLB 250 4MATIC, and GLB 35 4MATIC vehicles. The right-side front and rear tires may have sidewall damage, which can result in a sudden loss of tire pressure.

Remedy

Dealers will inspect and replace the tires as necessary, free of charge. Owner notification letters are expected to be mailed December 20, 2024. Owners may contact MBUSA customer service at 1-800-367-6372.

Vehicles

MAKE	MODEL	YEAR
MERCEDES-BENZ	AMG GLB35	2025
MERCEDES-BENZ	GLB 250	2025

Loss of Steering from Front Control Arm Separation

A detached control arm can cause a loss of vehicle steering and control, increasing the risk of a crash.

NHTSA Campaign Number: 24V770000

Manufacturer Ford Motor Company

Components SUSPENSION

Potential Number of Units Affected 2,416

Summary

Ford Motor Company (Ford) is recalling certain 2024 Ranger, and 2024-2025 Bronco vehicles. The front upper control arm ball joint nut may not have been installed or tightened properly, allowing the front upper control arm to detach from the knuckle assembly.

Remedy

Dealers will inspect and verify that the ball joint fastener is tightened properly. If a fastener is loose or missing, the dealer will replace the ball joint and knuckle assembly as necessary, free of charge. Owner notification letters are expected to be mailed on October 28, 2024. Owners may contact Ford Customer Service at 1-866-436-7332. Ford's number for this recall is 24S64.

Vehicles

MAKE	MODEL	YEAR
FORD	BRONCO	2024-2025
FORD	RANGER	2024

Loss of Power Brake Assist

A loss of power brake assist can extend the distance required to stop the vehicle. Additionally, a disabled antilock brake system and/or stability control system can result in a loss of vehicle control. Either of these scenarios can increase the risk of a crash.

NHTSA Campaign Number: 24V777000

Manufacturer Ford Motor Company

Components SERVICE BRAKES, HYDRAULIC

Potential Number of Units Affected 50

Summary

Ford Motor Company (Ford) is recalling certain 2021 Mach-E vehicles. An Over-The-Air (OTA) update to the Anti-lock Braking System (ABS) may result in a loss of power brake assist, ABS, Electronic Stability Control, Traction Control, and driver assistance features.

Remedy

Dealers will update the ABS calibration, free of charge. Owner notification letters are expected to be mailed November 4, 2024. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 24S65.

Vehicle

MAKE	MODEL	YEAR
FORD	MUSTANG MACH E	2021

Child Seat Anchors Not Attached Properly/FMVSS 225

A child seat that is not secured properly increases the risk of injury in the event of a crash.

NHTSA Campaign Number: 24V778000

Manufacturer Ford Motor Company

Components CHILD SEAT

Potential Number of Units Affected 6

Summary

Ford Motor Company (Ford) is recalling certain 2024 Maverick vehicles. The second-row child seat tether anchors may not properly secure a child seat, due to incomplete thread engagement. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 225, "Child Restraint Anchorage Systems."

Remedy

Dealers will repair the tether anchorage points, free of charge. Owner notification letters are expected to be mailed December 2, 2024. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 24C33.

Vehicle

MAKE	MODEL	YEAR
FORD	MAVERICK	2024

Brake Pedal Pushrod Screw Joint May Be Loose

A loose brake pedal can result in a loss of braking function, increasing the risk of a crash.

NHTSA Campaign Number: 24V788000

Manufacturer Volvo Car USA, LLC

Components SERVICE BRAKES, HYDRAULIC

Potential Number of Units Affected 291

Summary

Volvo Car USA, LLC (Volvo Car) is recalling certain 2020 S60, V60, S90I, XC60 and XC90 hybrid vehicles. The pushrod screw joint, connecting to the brake pedal to the hydraulic brake unit, may be loose.

Remedy

Dealers will tighten the brake pedal pushrod screw joint, free of charge. Owner notification letters are expected to be mailed December 17, 2024. Owners may contact Volvo Car customer service at 1-800-458-1552. Volvo's number for this recall is R10289.

Vehicles

MAKE	MODEL	YEAR
VOLVO	S60PHEV	2020
VOLVO	S90PHEV	2020
VOLVO	V60PHEV	2020

MAKE	MODEL	YEAR
VOLVO	XC60PHEV	2020
VOLVO	XC90PHEV	2020

Fuel Pump Failure May Cause Engine Stall

An engine stall increases the risk of a crash.

NHTSA Campaign Number: 24V789000

Manufacturer PACCAR Incorporated

Components FUEL SYSTEM, DIESEL

Potential Number of Units Affected 5,690

Summary

PACCAR Incorporated (PACCAR) is recalling certain 2025 Kenworth C500, T680, T800, T880, W900, W990, Peterbilt 567, 579, and 589 trucks, equipped with Cummins X15 diesel engines. The fuel pump barrels may fracture and cause a fuel leak, which can result in an engine stall.

Remedy

Dealers will replace the fuel pump barrels, free of charge. Owner notification letters are expected to be mailed December 22, 2024. Owners may contact Kenworth's customer service at 1-425-828-5888 and Peterbilt's customer service at 1-940-591-4220. Owners may also contact Cummins Customer Service at 812-377-5000. PACCAR's numbers for this recall are 24KWH and 24PBH.

Vehicles

MAKE	MODEL	YEAR
KENWORTH	C500	2025
KENWORTH	T680	2025
KENWORTH	T800	2025
KENWORTH	T880	2025

MAKE	MODEL	YEAR
KENWORTH	W900	2025
KENWORTH	W990	2025
PETERBILT	567	2025
PETERBILT	579	2025
PETERBILT	589	2025
