



# Automotive Safety Council

Prevent

Protect

Notify

## NHTSA Recalls of Interest

February 10, 2025

### Third-Row Seat Belt May Not Function/FMVSS 208

A non-functioning seat belt cannot properly restrain the seat occupant, increasing the risk of injury during a crash.

**NHTSA Campaign Number:** 25V056000

**Manufacturer** Honda (American Honda Motor Co.)

**Components** SEAT BELTS

**Potential Number of Units Affected** 1,494

#### Summary

Honda (American Honda Motor Co.) is recalling certain 2025 Honda Pilot vehicles. The third-row passenger seat belt assembly may not function, due to incorrect routing that traps the seat belt behind the passenger side panel. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 208, "Occupant Crash Protection."

#### Remedy

Dealers will inspect and repair the seat belt routing as necessary, free of charge. Owner notification letters are expected to be mailed March 24, 2025. Owners may contact Honda's customer service at 1-888-234-2138. Honda's number for this recall is ZL4.

#### Vehicle

---

MAKE	MODEL	YEAR
HONDA	PILOT	2025

---

## Forward Collision Sensing Radar May Fail

An inoperative radar increases the risk of a crash.

**NHTSA Campaign Number:** 25V044000

**Manufacturer** Autocar, LLC

**Components** FORWARD COLLISION AVOIDANCE

**Potential Number of Units Affected** 2

### Summary

Autocar, LLC (Autocar) is recalling certain 2024-2025 ACX (Xpeditor) vehicles. A software error may cause the forward collision sensing radar to fail.

### Remedy

Dealers will update the radar software, free of charge. Owner notification letters are expected to be mailed March 27, 2025. Owners may contact Autocar customer service at 1-888-218-3611. Autocar's number for this recall is ACX-2501.

### Vehicle

MAKE	MODEL	YEAR
AUTOCAR	XPEDITOR	2024-2025

## Loss of Drive Power

A loss of drive power increases the risk of a crash.

**NHTSA Campaign Number:** 25V046000

**Manufacturer** Daimler Trucks North America, LLC

**Components** ELECTRICAL SYSTEM

**Potential Number of Units Affected** 810

### Summary

Daimler Trucks North America, LLC (DTNA) is recalling certain 2020-2025 Freightliner eCascadia and 2022-2026 Freightliner eM2 trucks. The electric vehicle power distribution module (EVDM) may not be assembled properly, which can cause electrical circuits to disconnect and result in a loss of drive power.

### Remedy

The remedy is currently under development. Owner notification letters are expected to be mailed March 31, 2025. Owners may contact DTNA customer service at 1-800-547-0712. DTNA's number for this recall is F1017.

### Vehicles

MAKE	MODEL	YEAR
FREIGHTLINER	E-CASCADIA	2020-2025
FREIGHTLINER	EM2	2022-2026

## Rearview Camera Image May Not Display

Rearview camera failure can reduce the driver's view of what is behind the vehicle, increasing the risk of a crash.

**NHTSA Campaign Number:** 25V048000

**Manufacturer** Ford Motor Company

**Components** BACK OVER PREVENTION

**Potential Number of Units Affected** 72,624

### Summary

Ford Motor Company (Ford) is recalling certain 2021 Expedition, 2021-2022 Super Duty F-250, F-350, F-450, F-550, F-600, and 2020-2022 Lincoln Corsair vehicles. The rearview camera may display a blank or distorted image.

### Remedy

The remedy is currently under development. Owner notification letters are expected to be mailed February 17, 2025. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 25S05.

### Vehicles

MAKE	MODEL	YEAR
FORD	EXPEDITION	2021
FORD	F-250 SD	2021-2022
FORD	F-350 SD	2021-2022
FORD	F-450 SD	2021-2022

---

MAKE	MODEL	YEAR
FORD	F-550 SD	2021-2022
FORD	F-600 SD	2021-2022
LINCOLN	CORSAIR	2020-2022

---

## Instrument Panel Display Failure/FMVSS 101 & 102

An instrument panel display that fails to show critical safety information, such as the speedometer or warning lights, increases the risk of a crash.

**NHTSA Campaign Number:** 25V049000

**Manufacturer** Ford Motor Company

**Components** ELECTRICAL SYSTEM

**Potential Number of Units Affected** 298

### Summary

Ford Motor Company (Ford) is recalling certain 2025 Bronco Sport, Escape, and Lincoln Corsair vehicles. The Instrument Panel Cluster (IPC) may not illuminate at startup or while driving. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard numbers 101, "Control and Displays" and 102, "Transmission shift lever sequence, starter interlock, and transmission braking effect" as well as FMVSS numbers 126, 108, 135, 138, 208, and 305.

### Remedy

Dealers will replace the instrument panel cluster, free of charge. Owner notification letters are expected to be mailed February 10, 2025. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 25C02.

### Vehicles

---

MAKE	MODEL	YEAR
FORD	BRONCO SPORT	2025
FORD	ESCAPE	2025

---

---

MAKE	MODEL	YEAR
LINCOLN	CORSAIR	2025

---

## Exterior Lighting Switch Failure/FMVSS 101 & 108

Inoperative hazard lights cannot alert other drivers as intended. In addition, the inability to adjust the brightness on the instrument panel display can make it difficult to see critical safety information or distract the driver. Both scenarios can increase the risk of a crash.

**NHTSA Campaign Number:** 25V041000

**Manufacturer** PACCAR Incorporated

**Components** EXTERIOR LIGHTING, ELECTRICAL SYSTEM

**Potential Number of Units Affected** 5,378

### Summary

PACCAR Incorporated (PACCAR) is recalling certain 2025 Kenworth T180, Peterbilt 535, 567, 2025-2026 Kenworth T280, 2023-2026 Kenworth T380, 2024-2026 Kenworth T480, 2024-2026 Peterbilt 536, 537, and 548 trucks. The exterior lighting switch may fail, resulting in the hazard lights and the instrument display back-light brightness adjustment not functioning. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) numbers 101, "Control and Displays" and 108, "Lamps, Reflective Devices and Associated Equipment."

### Remedy

Dealers will update the vehicle cab controller unit (VECU) software, free of charge. Owners are advised that a non-responsive switch can be temporarily reset by a key cycle. Owner notification letters are expected to be mailed March 30, 2025. Owners may contact Kenworth's customer service at 1-425-828-5888 and Peterbilt's customer service at 1-940-591-4220. PACCAR's numbers for this recall are 25KWB and 25PBB.

### Vehicles

---

MAKE	MODEL	YEAR
KENWORTH	T180	2025
KENWORTH	T280	2025-2026
KENWORTH	T380	2023-2026

---

---

MAKE	MODEL	YEAR
KENWORTH	T480	2024-2026
PETERBILT	535	2025
PETERBILT	536	2024-2026
PETERBILT	537	2024-2026
PETERBILT	548	2024-2026
PETERBILT	567	2025

---

## Engine Stall and Rollaway Risk

A vehicle rollaway and an engine stall increase the risk of a crash.

**NHTSA Campaign Number:** 25V045000

**Manufacturer** Autocar, LLC

**Components** ELECTRICAL SYSTEM

**Potential Number of Units Affected** 130

### Summary

Autocar, LLC (Autocar) is recalling certain 2023-2025 E-ACTT vehicles. A software error may allow the vehicle to rollaway while on an incline and cause an engine stall.

### Remedy

Dealers will update the vehicle software, free of charge. Owner notification letters are expected to be mailed March 27, 2025. Owners may contact Autocar customer service at 1-888-218-3611. Autocar's number for this recall is ACTT-2501.

### Vehicle

---

MAKE	MODEL	YEAR
AUTOCAR	E-ACTT	2023-2025

---

## High Voltage Battery May Catch Fire

A vehicle fire while parked or driving can increase the risk of injury.

**NHTSA Campaign Number:** 25V050000

**Manufacturer** Mercedes-Benz USA, LLC

**Components** ELECTRICAL SYSTEM

**Potential Number of Units Affected** 7,362

### Summary

Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2022-2024 EQB 250, EQB 300 4MATIC, and EQB 350 4MATIC electric vehicles. The high voltage battery may fail internally and lead to a vehicle fire while parked or driving.

### Remedy

Owners are advised to only charge their vehicles to a maximum of 80% battery capacity until the repair has been completed. Dealers will update the battery management system software, free of charge. Owner notification letters are expected to be mailed April 1, 2025. Owners may contact MBUSA customer service at 1-800-367-6372.

### Vehicles

MAKE	MODEL	YEAR
MERCEDES-BENZ	EQB 250	2022-2024
MERCEDES-BENZ	EQB 300	2022-2024
MERCEDES-BENZ	EQB 350	2022-2024

## Battery May Short Circuit and Cause Fire

A high voltage battery that short circuits increases the risk of a fire.

**NHTSA Campaign Number:** 25V055000

**Manufacturer** Volvo Trucks North America

**Components** ELECTRICAL SYSTEM

**Potential Number of Units Affected** 13

## Summary

Volvo Trucks North America (Volvo Trucks) is recalling certain 2023-2025 VNR Electric trucks. The high voltage battery may contain loose hardware, which can create a short circuit inside the battery cells.

## Remedy

Dealers will replace the batteries, free of charge. Owner notification letters are expected to be mailed April 6, 2025. Owners may contact Volvo Trucks' customer service at 1-800-528-6586. Volvo Trucks' number for this recall is RVXX2501.

## Vehicle

---

MAKE	MODEL	YEAR
VOLVO	VNRE (ELECTRIC)	2023-2025

---