



# Automotive Safety Council

Prevent

Protect

Notify

## NHTSA Recalls of Interest

February 17, 2025

### Rear Side Air Bag May Not Deploy

A rear side air bag that does not deploy as intended can increase the risk of injury in a crash.

**NHTSA Campaign Number:** 25V064000

**Manufacturer** Hyundai Motor America

**Components** ELECTRICAL SYSTEM, AIR BAGS

**Potential Number of Units Affected** 33

#### Summary

Hyundai Motor America (Hyundai) is recalling certain 2025 IONIQ 5 EV vehicles. The rear floor wiring harness may contain an open circuit, which can result in the rear side air bag not deploying as intended.

#### Remedy

Dealers will inspect and replace the rear floor wiring harness, as necessary, free of charge. Owner notification letters are expected to be mailed April 7, 2025. Owners may contact Hyundai customer service at 1-855-371-9460. Hyundai's number for this recall is 274.

#### Vehicle

MAKE	MODEL	YEAR
HYUNDAI	IONIQ 5	2025

## Side Air Bag May Deploy Improperly/FMVSS 226

An air bag that deploys improperly increases the risk of ejection and injury during a crash.

**NHTSA Campaign Number:** 25V066000

**Manufacturer** ZEEKR TECHNOLOGY US, LLC

**Components** AIR BAGS, STRUCTURE

**Potential Number of Units Affected** 1

### Summary

Zeekr Technology US, LLC (Zeekr) is recalling one 2025 RT electric vehicle. The C-Pillar trim may catch the side curtain air bag, preventing the air bag from fully deploying. As such, this vehicle fails to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 226, "Ejection Mitigation."

### Remedy

Zeekr will modify the C-Pillar chutes, free of charge. The manufacturer has not yet provided a schedule for recall notification. Owners may contact Zeekr customer service at 1-212-481-2050.

### Vehicle

---

MAKE	MODEL	YEAR
ZEEKR	RT	2025

---

## Passenger Air Bag May Be Disabled/FMVSS 208

An air bag that deploys improperly or fails to deploy increases the risk of injury during a crash.

**NHTSA Campaign Number:** 25V067000

**Manufacturer** ZEEKR TECHNOLOGY US, LLC

**Components** AIR BAGS

**Potential Number of Units Affected** 1

### Summary

Zeekr Technology US, LLC (Zeekr) is recalling one 2025 RT vehicle. The Occupant Weight Sensor (OWS) may misclassify the front passenger seat occupant or disable the air bag. As such, this vehicle fails to comply with Federal Motor Vehicle Safety Standard (FMVSS) 208, "Occupant Crash Protection."

### Remedy

Zeekr will update the OWS software, free of charge. The manufacturer has not yet provided a schedule for recall notification. Owners may contact Zeekr customer service at 1-212-481-2050.

## Vehicle

---

MAKE	MODEL	YEAR
ZEEKR	RT	2025

---

## Air Bags Provide Inadequate Protection/FMVSS 208

Inadequate neck protection increases the risk of injury.

**NHTSA Campaign Number:** 25V068000

**Manufacturer** ZEEKR TECHNOLOGY US, LLC

**Components** SEATS, AIR BAGS

**Potential Number of Units Affected** 1

### Summary

Zeekr Technology US, LLC (Zeekr) is recalling one 2025 RT vehicle. The seat position may prevent the side curtain and passenger air bag from providing adequate neck protection during a crash. As such, this vehicle fails to comply with Federal Motor Vehicle Safety Standard (FMVSS) 208, "Occupant Crash Protection."

### Remedy

Zeekr will install a stop in the seat rail, free of charge. The manufacturer has not yet provided a schedule for recall notification. Owners may contact Zeekr customer service at 1-212-481-2050.

## Vehicle

---

MAKE	MODEL	YEAR
ZEEKR	RT	2025

---

## Damaged Second-Row Seat Belt/FMVSS 209

A damaged seat belt may not adequately restrain an occupant, increasing the risk of injury during a crash.

**NHTSA Campaign Number:** 25V059000

**Manufacturer** Toyota Motor Engineering & Manufacturing

**Components** SEAT BELTS

**Potential Number of Units Affected** 40,922

## Summary

Toyota Motor Engineering & Manufacturing (Toyota) is recalling certain 2025 Toyota Camry Hybrid, Lexus NX250, NX350, NX350 Hybrid, 2024-2025 Lexus RX350, RX350 Hybrid, and RX500 Hybrid vehicles. The second-row center seat belt webbing may be damaged. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 209, "Seat Belt Assemblies."

## Remedy

Dealers will inspect the seat belt webbing and replace the seat belt assembly if necessary, free of charge. Owner notification letters are expected to be mailed March 24, 2025. Owners may contact Toyota's customer service at 1-800-331-4331. Toyota's numbers for this recall are 25TA03 and 25LA03.

## Vehicles

MAKE	MODEL	YEAR
LEXUS	NX	2025
LEXUS	NX HYBRID	2025
LEXUS	RX	2024-2025
LEXUS	RX HYBRID	2024-2025
TOYOTA	CAMRY HYBRID	2025

## Rear Seat Belt Buckles Not Tightened Properly

A loose seat belt buckle may not properly restrain an occupant during a crash, increasing the risk of injury.

**NHTSA Campaign Number:** 25V078000

**Manufacturer** Porsche Cars North America, Inc.

**Components** SEAT BELTS

**Potential Number of Units Affected** 279

## Summary

Porsche Cars North America, Inc. (Porsche) is recalling certain 2023 911 vehicles. The bolts for the rear seat belt buckles may not be tightened properly.

## Remedy

Dealers will inspect and tighten the rear seat belt buckle bolt, and reposition the aluminum butyl soundproofing mat as necessary, free of charge. Owner notification letters are expected to be mailed April 11, 2025. Owners may contact Porsche customer service at 1-800-767-7243. Porsche's number for this recall is ASA0.

## Vehicle

---

MAKE	MODEL	YEAR
PORSCHE	911	2023

---

## Reduced Braking Performance from Software Error

Reduced braking performance can increase the distance required to stop the vehicle, increasing the risk of a crash.

**NHTSA Campaign Number:** 25V065000

**Manufacturer** Hyundai Motor America

**Components** SERVICE BRAKES, HYDRAULIC

**Potential Number of Units Affected** 1,508

### Summary

Hyundai Motor America (Hyundai) is recalling certain 2025 Hyundai IONIQ 5 "N" vehicles equipped with a left-foot braking (LFB) feature. The integrated electronic brake (IEB) and vehicle control unit (VCU) software may cause reduced braking performance when LFB is activated.

## Remedy

Owners are advised not to use the LFB feature until the remedy has been performed. Dealers will update the IEB and VCU software, free of charge. Owner notification letters are expected to be mailed April 7, 2025. Owners may contact Hyundai customer service at 1-855-371-9460. Hyundai's number for this recall is 275.

## Vehicle

---

MAKE	MODEL	YEAR
HYUNDAI	IONIQ 5	2025

---

## Excessive Glare from Headlight Low Beams/FMVSS 108

Excessive glare can decrease the visibility to oncoming drivers, increasing the risk of a crash.

**NHTSA Campaign Number:** 25V079000

**Manufacturer** Porsche Cars North America, Inc.

**Components** EXTERIOR LIGHTING

**Potential Number of Units Affected** 878

### Summary

Porsche Cars North America, Inc. (Porsche) is recalling certain 2025 911 vehicles. A software error in the front-end electronics control module may result in the low beam headlights creating a glare for oncoming traffic. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 108, "Lamps, Reflective Devices, and Associated Equipment."

### Remedy

Dealers will update the front-end electronics control module software, free of charge. Owner notification letters are expected to be mailed April 11, 2025. Owners may contact Porsche customer service at 1-800-767-7243. Porsche's number for this recall is ASA1.

### Vehicle

---

MAKE	MODEL	YEAR
PORSCHE	911	2025

---

## Headlight Shutters May Close Unexpectedly

### Software Update Repairs Recall

A loss of headlight function while driving can reduce visibility and increase the risk of a crash.

**NHTSA Campaign Number:** 25V071000

**Manufacturer** Volvo Car USA, LLC

**Components** EXTERIOR LIGHTING, ELECTRICAL SYSTEM

**Potential Number of Units Affected** 2,061

### Summary

Volvo Car USA, LLC (Volvo) is recalling certain 2025 EX90 vehicles. Due to a software error in the low power controller (LPC), the headlight shutters may close over the high and low beams while driving.

### Remedy

The LPC software will be updated through an over-the-air (OTA) update or by a dealer, free of charge. Owner notification letters are expected to be mailed April 3, 2025. Owners may contact Volvo's customer service at 1-800-458-1552. Volvo's number for this recall is R10298.

## Vehicle

---

MAKE	MODEL	YEAR
VOLVO	EX90	2025

---

## TPMS Warning Light Malfunction/FMVSS 138

A TPMS warning light that fails to notify the driver of a problem increases the risk of a crash.

**NHTSA Campaign Number:** 25V063000

**Manufacturer** ZEEKR TECHNOLOGY US, LLC

**Components** ELECTRICAL SYSTEM, TIRES, EQUIPMENT

**Potential Number of Units Affected** 1

### Summary

Zeekr Technology US, LLC (Zeekr) is recalling one 2025 RT vehicle. The digital tire pressure monitoring system (TPMS) warning light may not flash long enough for the driver to notice. Additionally, the owner's manual may be missing information about the TPMS warning light. As such, this vehicle fails to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 138, "Tire Pressure Monitoring Systems."

### Remedy

Zeekr will update the display head unit software and add a correction to the owner's manual, free of charge. The manufacturer has not yet provided a schedule for recall notification. Owners may contact Zeekr customer service at 1-212-481-2050.

## Vehicle

---

MAKE	MODEL	YEAR
ZEEKR	RT	2025

---

## Rear Brake Hose May Leak

A brake fluid leak can reduce braking ability and increase the risk of a crash.

**NHTSA Campaign Number:** 25V058000

**Manufacturer** Toyota Motor Engineering & Manufacturing

**Components** SERVICE BRAKES, HYDRAULIC

**Potential Number of Units Affected** 106,061

## Summary

Toyota Motor Engineering & Manufacturing (Toyota) is recalling certain 2024-2025 Tacoma 4-wheel drive vehicles. The rear brake hoses can be damaged if mud and dirt builds up inside the rear wheels. This can result in a brake fluid leak.

## Remedy

Dealers will replace both rear brake hoses, free of charge. Interim letters notifying owners of the safety risk are expected to be mailed March 24, 2025. A second letter will be sent once the remedy is available. Owners may contact Toyota's customer service at 1-800-331-4331. Toyota's numbers for this recall are 25TB04 and 25TA04.

## Vehicle

---

MAKE	MODEL	YEAR
TOYOTA	TACOMA	2024-2025

---