



# Automotive Safety Council

Prevent Protect Notify

## NHTSA Recalls of Interest

October 11, 2022

### Seatback Lock Failure

**NHTSA Campaign Number:** 22V732000

**Manufacturer** Mercedes-Benz USA, LLC

**Components** SEATS

**Potential Number of Units Affected** 59,574

#### **Summary**

Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2021 AMG GLS63, 2020-2022 GLS450 and GLS580 vehicles. Due to a manufacturing error, the locks on the third-row seatbacks may fail in the event of a crash.

#### **Remedy**

Dealers will inspect and replace the third-row seatback, as necessary, free of charge. Owner notification letters are expected to be mailed November 29, 2022. Owners may contact MBUSA customer service at 1-800-367-6372.

#### **Vehicles**

MAKE	MODEL	YEAR
MERCEDES-BENZ	AMG GLS63	2021
MERCEDES-BENZ	GLS450	2020-2022
MERCEDES-BENZ	GLS580	2020-2022

## Loose Bolt in Driver's Seat Frame

**NHTSA Campaign Number:** 22V724000

**Manufacturer** General Motors, LLC

**Components** SEATS

**Potential Number of Units Affected** 7,571

### **Summary**

General Motors, LLC (GM) is recalling certain 2022-2023 Chevrolet Equinox and 2022 GMC Terrain vehicles. The driver's seat may have a stripped or loose bolt at the seat frame height-adjust pivot.

### **Remedy**

Dealers will inspect the driver's seat and replace the seat cushion frame, if necessary, free of charge. Owner notification letters are expected to be mailed November 14, 2022. Owners may contact Chevrolet customer service at 1-800-222-1020 or GMC customer service at 1-800-462-8782. GMC's number for this recall is N222377890.

### **Vehicles**

MAKE	MODEL	YEAR
------	-------	------

CHEVROLET	EQUINOX	2022-2023
-----------	---------	-----------

GMC	TERRAIN	2022
-----	---------	------

## Steering Knuckle and Control Arm May Separate

**NHTSA Campaign Number:** 22V744000

**Manufacturer** Rivian Automotive, LLC

**Components** SUSPENSION, STEERING

**Potential Number of Units Affected** 12,212

### **Summary**

Rivian Automotive, LLC (Rivian) is recalling certain 2022 R1T, R1S, and EDV vehicles. The fastener connecting the front upper control arm and steering knuckle may have been improperly tightened.

### **Remedy**

Dealers will inspect and, as necessary, tighten the steering knuckle fastener, free of charge. Owner notification letters are expected to be mailed November 24, 2022. Owners may contact Rivian customer service at 1-888-748-4261. Rivian's number for this recall is FSAM 997.

## Vehicles

### MAKE MODEL YEAR

RIVIAN EDV	2022
RIVIAN R1S	2022
RIVIAN R1T	2022

## Disabled Safety Features from Unsecure 12V Battery

**NHTSA Campaign Number:** 22V733000

**Manufacturer** Mercedes-Benz USA, LLC

**Components** ELECTRICAL SYSTEM

**Potential Number of Units Affected** 19,968

### Summary

Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2019-2022 CLS450 Coupe and AMG E53, 2019-2021 AMG CLS53 Coupe, and 2021-2022 E450 vehicles. The 12-Volt battery in the trunk may not be properly secured, which, in the event of a crash, can cause electrical connection failure, disabling various safety features including, emergency call (eCall) system, electric seat adjustment, hazard warning lights, and automatic door locks.

### Remedy

Dealers will secure the 12V battery, free of charge. Owner notification letters are expected to be mailed November 29, 2022. Owners may contact MBUSA customer service at 1-800-367-6372.

## Vehicles

### MAKE MODEL YEAR

MERCEDES-BENZ	AMG CLS53	2019-2021
MERCEDES-BENZ	AMG E53	2019-2022
MERCEDES-BENZ	CLS450	2019-2022
MERCEDES-BENZ	E450	2021-2022

## Front Parking Light Malfunction/FMVSS 108

**NHTSA Campaign Number:** 22V725000

**Manufacturer** BMW of North America, LLC

## **Components EXTERIOR LIGHTING**

**Potential Number of Units Affected** 3,315

### **Summary**

BMW of North America, LLC (BMW) is recalling certain 2023 X7 xDrive40i, and X7 M60i vehicles. In certain vehicle operating conditions, only one of the two front parking lights may remain illuminated. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 108, "Lamps, Reflective Devices, and Associated Equipment."

### **Remedy**

Dealers will reprogram the electronic control unit for the front parking lights, free of charge. Owner notification letters are expected to be mailed November 21, 2022. Owners may contact BMW customer service at 1-800-525-7417.

### **Vehicle**

#### **MAKE MODEL YEAR**

BMW X7 2023

## **Headlights Missing Metallic Coating/FMVSS 108**

**NHTSA Campaign Number:** 22V721000

**Manufacturer** BMW of North America, LLC

## **Components EXTERIOR LIGHTING**

**Potential Number of Units Affected** 2

### **Summary**

BMW of North America, LLC (BMW) is recalling certain 2023 Rolls-Royce Phantom vehicles. The headlights may not have received a metal coating application, which can result in the low beams not adequately illuminating road signs. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 108, "Lamps, Reflective Devices, and Associated Devices."

### **Remedy**

Dealers will replace the headlights, free of charge. The affected vehicles are still at dealerships and therefore no owner notification letters will be mailed. Owners may contact Rolls-Royce customer service at 1-877-877-3735.

### **Vehicle**

**MAKE      MODEL   YEAR**

ROLLS-ROYCE PHANTOM 2023