

NHTSA Recalls of Interest

July 22, 2024

Vehicle Roll Away from Software Error

A vehicle roll away increases the risk of a crash or injury.

NHTSA Campaign Number: 24V529000

Manufacturer Hyundai Motor America

Components POWER TRAIN

Potential Number of Units Affected 12,349

Summary

Hyundai Motor America (Hyundai) is recalling certain 2024 Santa Fe vehicles. A software error in the transmission control unit may result in a vehicle roll away when the vehicle is in PARK.

Remedy

Owners are advised to use the emergency parking brake after parking their vehicles. Dealers will update transmission control unit software. In addition, dealers will inspect and replace the dual clutch transmission, as necessary. All repairs will be performed free of charge. Owner notification letters are expected to be mailed September 9, 2024. Owners may contact Hyundai customer service at 1-855-371-9460. Hyundai's number for this recall is 263.

Vehicle

MAKE	MODEL	YEAR
HYUNDAI	SANTA FE	2024

Driver's Air Bag Inflator May Explode

An inflator explosion may result in sharp metal fragments striking the driver or other occupants, increasing the risk of injury or death.

NHTSA Campaign Number: 24V527000

Manufacturer BMW of North America, LLC

Components AIR BAGS

Potential Number of Units Affected 1,145

Summary

BMW of North America, LLC (BMW) is recalling certain 2015 6 Series Gran Coupe, 2014 5 Series Gran Turismo, 2014 5 Series Sedan, 2015 6 Series Convertible, 2015 6 Series Coupe, 2014 X5, 2013-2014 X3, 2014-2015 3 Series Sedan, 2014 4 Series Coupe, 2014 4 Series Convertible, 2014 3 Series Gran Turismo, and 2015 4 Series Gran Coupe vehicles. Please see the recall report for the complete list of models. The driver's air bag inflator may explode during deployment, due to a manufacturing defect.

Remedy

The driver's front air bag will be replaced, free of charge. Owner notification letters are expected to be mailed September 2, 2024. Owners may contact BMW customer service at 1-800-525-7417.

MAKE	MODEL	YEAR
BMW	3201	2014-2015
BMW	328D	2014
BMW	328I	2014-2015
BMW	335I	2014-2015
BMW	428I	2014-2015
BMW	435I	2014
BMW	528I	2014

Vehicles

MAKEMODELYEARBMW535D2014BMW53512014BMW550I2014BMW640I2015BMW650I2015BMWACTIVEHYBRID 52014BMWM42014BMWX32013-2014BMWX52014			
BMW 535I 2014 BMW 550I 2014 BMW 640I 2015 BMW 650I 2015 BMW ACTIVEHYBRID 5 2014 BMW M4 2013-2014	MAKE	MODEL	YEAR
BMW 550I 2014 BMW 640I 2015 BMW 650I 2015 BMW ACTIVEHYBRID 5 2014 BMW M4 2014 BMW X3 2013-2014	BMW	535D	2014
BMW 640I 2015 BMW 650I 2015 BMW ACTIVEHYBRID 5 2014 BMW M4 2014 BMW X3 2013-2014	BMW	5351	2014
BMW 650I 2015 BMW ACTIVEHYBRID 5 2014 BMW M4 2014 BMW X3 2013-2014	BMW	550I	2014
BMW ACTIVEHYBRID 5 2014 BMW M4 2014 BMW X3 2013-2014	BMW	640I	2015
BMW M4 2014 BMW X3 2013-2014	BMW	650I	2015
BMW X3 2013-2014	BMW	ACTIVEHYBRID 5	2014
	BMW	M4	2014
BMW X5 2014	BMW	X3	2013-2014
	BMW	X5	2014

Front Axle Arm Control May Break

A sudden loss of steering control increases the risk of a crash.

NHTSA Campaign Number: 24V533000

Manufacturer Porsche Cars North America, Inc.

Components SUSPENSION

Potential Number of Units Affected 2,475

Summary

Porsche Cars North America, Inc. (Porsche) is recalling certain 2024 Cayenne vehicles. The driver's side front axle upper left control arm installed on the vehicles may have been installed with cracks. which can result in front axle control arm breaking and an unexpected loss of steering and wheel control.

Remedy

Dealers will replace the driver side left upper control arm, free of charge. Owner letters are expected to be mailed September 13, 2024. Owners may contact Porsche customer service at 1-800-767-7243. Porsche's number for this recall is ARB2.

Vehicle

MAKE	MODEL	YEAR
PORSCHE	CAYENNE	2024

Loss of Drive Power from Fuel Pump Failure

A loss of drive power can increase the risk of a crash.

NHTSA Campaign Number: 24V528000

Manufacturer Hyundai Motor America

Components FUEL SYSTEM, GASOLINE

Potential Number of Units Affected 54,647

Summary

Hyundai Motor America (Hyundai) is recalling certain 2019-2022 Veloster N, 2019-2023 Genesis G70, 2022-2023 Elantra N, and Kona N vehicles. The fuel pump may fail, which can result in a loss of drive power.

Remedy

Dealers will update engine control module software. In addition, dealers will inspect and replace the fuel pump assembly, as necessary. All repairs will be performed free of charge. Owner notification letters are expected to be mailed September 9, 2024. Owners may contact Hyundai customer service at 1-855-371-9460. Hyundai's numbers for this recall are 262 and 023G.

Vehicles

MAKE	MODEL	YEAR
GENESIS	G70	2019-2023
HYUNDAI	ELANTRA N	2022-2023

МАКЕ	MODEL	YEAR
HYUNDAI	KONA N	2022-2023
HYUNDAI	VELOSTER N	2019-2022