

NHTSA Recalls of Interest September 2, 2024

Fuel Injectors May Leak

A fuel leak in the presence of an ignition source increases the risk of a fire.

NHTSA Campaign Number: 24V634000

Manufacturer Ford Motor Company

Components FUEL SYSTEM, GASOLINE

Potential Number of Units Affected 24

Summary

Ford Motor Company (Ford) is recalling certain 2023 Lincoln Corsair, 2023-2024 Escape, 2024 Mustang, and 2025 Explorer vehicles. The fuel injectors may have been assembled without O-ring support discs, which can result in a fuel leak.

Remedy

Dealers will install new fuel injector O-rings and O-ring support discs, free of charge. Owner notification letters are expected to be mailed September 30, 2024. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 24S54.

Vehicles

MAKE	MODEL	YEAR
FORD	ESCAPE	2023-2024

MAKE	MODEL	YEAR
FORD	EXPLORER	2025
FORD	MUSTANG	2024
LINCOLN	CORSAIR	2023

Engine Intake Valves May Break

A loss of drive power increases the risk of a crash.

NHTSA Campaign Number: 24V635000

Manufacturer Ford Motor Company

Components ENGINE AND ENGINE COOLING

Potential Number of Units Affected 90,736

Summary

Ford Motor Company (Ford) is recalling certain 2021-2022 Bronco, F-150, Edge, Explorer, Lincoln Nautilus, and Lincoln Aviator vehicles equipped with either a 2.7L or 3.0L Nano EcoBoost engine. The engine intake valves may break while driving, which can result in engine failure and a loss of drive power.

Remedy

Dealers will perform an engine cycle test and replace the engine as necessary, free of charge. Owner notification letters are expected to be mailed October 7, 2024. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 24S55.

Vehicles

MAKE	MODEL	YEAR
FORD	BRONCO	2021-2022
FORD	EDGE	2021-2022
FORD	EXPLORER	2021-2022

MAKE	MODEL	YEAR	
FORD	F-150	2021-2022	
LINCOLN	AVIATOR	2021-2022	
LINCOLN	NAUTILUS	2021-2022	

High-Voltage Battery May Overheat

A high-voltage battery that overheats increases the risk of a fire.

NHTSA Campaign Number: 24V633000

Manufacturer Jaguar Land Rover North America, LLC

Components ELECTRICAL SYSTEM

Potential Number of Units Affected 2,760

Summary

Jaguar Land Rover North America, LLC (Jaguar) is recalling certain 2019 Jaguar I-PACE vehicles. The high-voltage battery may overheat.

Remedy

Owners are advised to park and charge their vehicle outside and away from structures until the recall repair is complete and for 30 days after the repair has been completed. As an interim repair, dealers will update the battery energy control module software, free of charge. The final remedy is currently under development. Owner notification letters are expected to be mailed October 18, 2024. Owners may contact Jaguar customer service at 1-800-452-4827. Jaguar's number for this recall is H514. These vehicles were previously recalled for this same issue under one or more recall numbers 24V-085 (H471), 23V-709 (H459), or 23V-369 (H441) and will need to have the new remedy performed.

Vehicle

MAKE	MODEL	YEAR
JAGUAR	I-PACE	2019