



Automotive Safety Council

Prevent

Protect

Notify

NHTSA Recalls of Interest

September 16, 2024

Incorrect Headlight Software/FMVSS 108

Incorrect headlight control module software may cause the parking lights not to operate as intended when the turn signals are activated, which can reduce vehicle visibility and increase the risk of a crash.

NHTSA Campaign Number: 24V654000

Manufacturer Porsche Cars North America, Inc.

Components EXTERIOR LIGHTING

Potential Number of Units Affected 954

Summary

Porsche Cars North America, Inc. (Porsche) is recalling certain 2024 Taycan vehicles. The incorrect headlight control module software may have been installed. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 108, "Lamps, Reflective Devices, and Associated Equipment."

Remedy

Dealers will update the headlight control module software, free of charge. Owner notification letters are expected to be mailed November 1, 2024. Owners may contact Porsche customer service at 1-800-767-7243. Porsche's number for this recall is ARB4.

Vehicle

MAKE	MODEL	YEAR
PORSCHE	TAYCAN	2024

Vehicle Doors May Open Unexpectedly

A vehicle door that opens unexpectedly while driving increases the risk of injury.

NHTSA Campaign Number: 24V651000

Manufacturer Volkswagen Group of America, Inc.

Components STRUCTURE

Potential Number of Units Affected 98,806

Summary

Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2021-2024 ID.4 vehicles. The door handles may allow water to enter the circuit board assembly, which can cause the doors to open unexpectedly.

Remedy

Volkswagen dealers will inspect and replace the door handles as necessary, and update the vehicle software, free of charge. Owner notification letters are expected to be mailed November 1, 2024. Owners may contact Volkswagen's customer service at 1-800-893-5298. Volkswagen's number for this recall is 57J9. This recall expands previous recall numbers 23V-312 and 23V-213. Vehicles previously repaired under 23V-312 and 23V-213 will need to have the new remedy completed.

Vehicle

MAKE	MODEL	YEAR
VOLKSWAGEN	ID.4	2021-2024

Forward Sensing Camera Malfunction

Automatic braking, steering assist, and headlight control systems that do not function as intended can increase the risk of a crash.

NHTSA Campaign Number: 24V649000

Manufacturer Mazda North American Operations

Components LANE DEPARTURE, EXTERIOR LIGHTING, FORWARD COLLISION AVOIDANCE

Potential Number of Units Affected 672

Summary

Mazda North American Operations (Mazda) is recalling certain 2024 Mazda 3, CX-30, and 2025 CX-50 vehicles. A malfunction in the forward sensing camera (FSC) may prevent the automatic emergency braking system and the lane-keep assist system from functioning. In addition, the headlights will not automatically adjust from high beams to low beams as intended.

Remedy

Dealers will inspect and replace the forward sensing camera as necessary, free of charge. Owner notification letters are expected to be mailed November 2, 2024. Owners may contact Mazda customer service at 1-800-222-5500, Option 6. Mazda's number for this recall is 6824H.

Vehicles

MAKE	MODEL	YEAR
MAZDA	CX-30	2024
MAZDA	CX-50	2025
MAZDA	MAZDA3	2024
