



Automotive Safety Council

Prevent

Protect

Notify

NHTSA Recalls of Interest

November 25, 2024

Air Bags May Not Deploy as Intended

Air bags that do not deploy as intended during a crash increases the risk of injury.

NHTSA Campaign Number: 24V870000

Manufacturer BMW of North America, LLC

Components AIR BAGS

Potential Number of Units Affected 3

Summary

BMW of North America, LLC (BMW) is recalling certain 2025 530i and 540i xDrive vehicles. The air bag control unit may have been manufactured incorrectly, which can result in the air bags not deploying as intended.

Remedy

Dealers will replace the air bag control unit, free of charge. The vehicles have not been sold from dealer inventory and therefore no owner letters will be mailed. Owners may contact BMW customer service at 1-800-525-7417.

Vehicles

MAKE	MODEL	YEAR
BMW	530I	2025

MAKE	MODEL	YEAR
BMW	540I XDRIVE	2025

Driver's Seat Frame Improperly Tightened/FMVSS 207

An unsecured driver's seat may not adequately restrain the driver during a crash, increasing the risk of injury.

NHTSA Campaign Number: 24V859000

Manufacturer Honda (American Honda Motor Co.)

Components SEATS

Potential Number of Units Affected 121

Summary

Honda (American Honda Motor Co.) is recalling certain 2023-2024 Honda Accord, Accord Hybrid, Civic Sedan, Civic Hatchback, Pilot, and 2024 HR-V, Acura Integra and Acura Integra Type S vehicles. The driver's seat cushion frame may not have been tightened properly, which can result in an unsecured seat. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 207, "Seating Systems."

Remedy

Dealers will replace the driver's seat cushion frame, free of charge. Owner notification letters are expected to be mailed January 6, 2025. Owners may contact Honda customer service at 1-888-234-2138.

Vehicles

MAKE	MODEL	YEAR
ACURA	INTEGRA	2024
ACURA	INTEGRA TYPE S	2024
HONDA	ACCORD	2023-2024
HONDA	ACCORD HYBRID	2023-2024

MAKE	MODEL	YEAR
HONDA	CIVIC	2023-2024
HONDA	CIVIC HATCHBACK	2023-2024
HONDA	HR-V	2024
HONDA	PILOT	2023-2024

Missing Rear Vision Camera Video Display/FMVSS 111

A missing rear vision camera display reduces the driver's visibility behind the vehicle, increasing the risk of a crash.

NHTSA Campaign Number: 24V858000

Manufacturer General Motors, LLC

Components BACK OVER PREVENTION

Potential Number of Units Affected 582

Summary

General Motors, LLC (GM) is recalling certain 2024 Chevrolet Express Commercial Cutaway and GMC Savana Commercial Cutaway vehicles. These vehicles may be missing the required rear vision camera video display because an incorrect inside rearview mirror was installed. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 111, "Rear Visibility."

Remedy

Dealers will inspect and replace the inside rearview mirror as necessary, free of charge. Owner notification letters are expected to be mailed December 30, 2024. Owners may contact GM customer service at 1-888-988-7267, and Chevrolet at 1-800-222-1020. GM's number for this recall is N242481860.

Vehicles

MAKE	MODEL	YEAR
CHEVROLET	EXPRESS CUTAWAY VAN	2024

MAKE	MODEL	YEAR
GMC	SAVANA CUTAWAY VAN	2024

Fuel Pump May Fail

Fuel pump failure can cause an engine stall, increasing the risk of a crash.

NHTSA Campaign Number: 24V864000

Manufacturer Honda (American Honda Motor Co.)

Components FUEL SYSTEM, GASOLINE

Potential Number of Units Affected 40,481

Summary

Honda (American Honda Motor Co.) is recalling certain 2007, 2009-2017 CBR600RR, 2008, 2017, 2019, 2021 CBR1000RR, and 2010, 2012-2013 VFR1200 motorcycles. The fuel pump impellers may have been improperly molded, which can cause them to deform and result in fuel pump failure.

Remedy

Dealers will inspect and replace the fuel pump module as necessary, free of charge. Owner letters are expected to be mailed January 6, 2025. Owners may contact Honda customer service at 1-866-784-1870. This recall is an expansion of NHTSA recall number 24V-113.

Vehicles

MAKE	MODEL	YEAR
HONDA	CBR1000RR	2008, 2017, 2019, 2021
HONDA	CBR600RR	2007, 2009-2017
HONDA	VFR1200F	2010, 2012-2013
HONDA	VFR1200FD	2010, 2012-2013

Loss of Drive Power from Damaged Charging Unit

A loss of drive power increases the risk of a crash.

NHTSA Campaign Number: 24V867000

Manufacturer Kia America, Inc.

Components ELECTRICAL SYSTEM

Potential Number of Units Affected 62,872

Summary

Kia America, Inc. (Kia) is recalling certain 2022-2024 EV6 vehicles. The Integrated Charging Control Unit (ICCU) may become damaged and stop charging the 12-volt battery, which can result in a loss of drive power.

Remedy

Dealers will inspect and replace the ICCU and its fuse, as necessary. In addition, dealers will update the ICCU software. All repairs will be performed free of charge. Owner notification letters are expected to be mailed December 13, 2024. Owners may contact Kia customer service at 1-800-333-4542. Kia's number for this recall is SC327. This recall expands and replaces previous recall number 24V-200. Vehicles previously repaired under recall 24V-200 will need to have the new remedy completed.

Vehicle

MAKE	MODEL	YEAR
KIA	EV6	2022-2024

Incorrect Vehicle Speed Displayed/ FMVSS 101

Driving without knowing the vehicle's actual speed increases the risk of a crash.

NHTSA Campaign Number: 24V872000

Manufacturer Chrysler (FCA US, LLC)

Components ELECTRICAL SYSTEM

Potential Number of Units Affected 7,198

Summary

Chrysler (FCA US, LLC) is recalling certain 2024 Jeep Grand Cherokee and Grand Cherokee L vehicles. A software error in the instrument panel cluster may cause the speedometer to display the incorrect vehicle speed. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 101, "Displays and Controls."

Remedy

Dealers will inspect and update the instrument panel cluster software as necessary, free of charge. Owner notification letters are expected to be mailed December 17, 2024. Owners may contact FCA customer service at 1-800-853-1403. FCA's number for this recall is B8B.

Vehicles

MAKE	MODEL	YEAR
JEEP	GRAND CHEROKEE	2024
JEEP	GRAND CHEROKEE L	2024

Defective Coolant Sensor May Shut Down Engine

An unexpected engine shut down can increase the risk of a crash. Additionally, transferring passengers from the disabled bus can increase the risk of injury.

NHTSA Campaign Number: 24V873000

Manufacturer Nova Bus (US) Inc.

Components ENGINE AND ENGINE COOLING

Potential Number of Units Affected 673

Summary

Nova Bus (US) Inc. (Nova Bus) is recalling certain 2023 LFS Artic and 2023-2024 LFS buses. The coolant sensor could send a false signal, causing the engine to shut down.

Remedy

Nova Bus will inspect and replace the coolant sensor as necessary, free of charge. Owner notification letters are expected to be mailed January 18, 2025. Owners may contact Nova Bus customer service at 1-800-350-6682. Nova Bus's number for this recall is CR5668.

Vehicles

MAKE	MODEL	YEAR
NOVA BUS	LFS	2023-2024
NOVA BUS	LFS ARTIC	2023

Rearview Camera Image May Not Display/FMVSS 111

A blank rearview camera display can reduce the driver's rear visibility, increasing the risk of a crash.

NHTSA Campaign Number: 24V875000

Manufacturer Volkswagen Group of America, Inc.

Components BACK OVER PREVENTION

Potential Number of Units Affected 385

Summary

Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2023 ID.4 vehicles. The rearview camera image may not display when the vehicle is placed in reverse or when the park function is manually activated. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 111, "Rear Visibility."

Remedy

Dealers will replace the peripheral camera control module, free of charge. Owner notification letters are expected to be mailed January 17, 2025. Owners may contact Volkswagen customer service at 1-800-893-5298. Volkswagen's number for this recall is 91B3.

Vehicle

MAKE	MODEL	YEAR
VOLKSWAGEN	ID.4	2023
