



Automotive Safety Council

Prevent

Protect

Notify

NHTSA Recalls of Interest

December 30, 2024

Missing Seat Mounting Bolts

Seats without mounting bolts may not properly restrain an occupant, increasing the risk of injury.

NHTSA Campaign Number: 24V962000

Manufacturer Kia America, Inc.

Components SEATS

Potential Number of Units Affected 22,883

Summary

Kia America, Inc. (Kia) is recalling certain 2024-2025 EV9 vehicles. The second- and third-row seat mounting bolts may be missing.

Remedy

Dealers will inspect and install mounting bolts as necessary free of charge. Owner notification letters are expected to be mailed January 24, 2025. Owners may contact Kia customer service at 1-800-333-4542. Kia's number for this recall is SC329.

Vehicle

MAKE	MODEL	YEAR
KIA	EV9	2024-2025

Loss of Steering from Front Control Arm Separation

A detached control arm can cause a loss of vehicle steering and control, increasing the risk of a crash.

NHTSA Campaign Number: 24V949000

Manufacturer Ford Motor Company

Components SUSPENSION

Potential Number of Units Affected 11,922

Summary

Ford Motor Company (Ford) is recalling certain 2023-2024 F-150 Lightning BEV vehicles. The front upper control arm ball joint nut may not have been tightened properly, allowing the front upper control arm to detach from the knuckle assembly.

Remedy

Dealers will inspect the upper control arm ball joint nut, and replace the nut and/or knuckle assembly, as necessary, free of charge. Owner notification letters are expected to be mailed February 3, 2025. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 24S76.

Vehicle

MAKE	MODEL	YEAR
FORD	F-150 LIGHTNING	2023-2024
