

# NHTSA Recalls of Interest March 17, 2025

## Seat Belt Buckle May Not Latch

An unlatched seat belt will not properly restrain an occupant, increasing the risk of injury.

NHTSA Campaign Number: 25V155000 Manufacturer Jaguar Land Rover North America, LLC

**Components SEAT BELTS** 

Potential Number of Units Affected 7,276

#### Summary

Jaguar Land Rover North America, LLC (Land Rover) is recalling certain 2025 Range Rover and Range Rover Sport vehicles. The second-row center seat belt buckle may not latch correctly due to a manufacturing error.

#### Remedy

Dealers will replace the center seat belt buckle and buckle retaining bolt, free of charge. Owner notification letters are expected to be mailed May 2, 2025. Owners may contact Land Rover's customer service at 800-637-6837. Land Rover's number for this recall is N989.

#### Vehicles

MAKE	MODEL	YEAR
LAND ROVER	RANGE ROVER	2025

МАКЕ	MODEL	YEAR
LAND ROVER	RANGE ROVER SPORT	2025

## Improperly Secured Seat Frame /FMVSS 207 & 210

An unsecured driver's seat may not adequately restrain the driver during a crash, increasing the risk of injury.

#### NHTSA Campaign Number: 25V153000

Manufacturer Nissan North America, Inc.

Components SEATS

Potential Number of Units Affected 199

#### Summary

Nissan North America, Inc. (Nissan) is recalling certain 2025 Sentra vehicles. The driver's seat frame may not be fully secured to the outer side of the seat track. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard numbers 207, "Seating Systems," and 210, "Seat Belt Assembly Anchorages."

#### Remedy

Dealers will inspect and replace the driver's side lower seat frame assembly as necessary, free of charge. Owner notification letters are expected to be mailed May 1, 2025. Owners may contact Nissan's customer service at 1-800-867-7669. Nissan's number for this recall is PMA45.

#### Vehicle

MAKE	MODEL	YEAR
NISSAN	SENTRA	2025

## Transmission Damage May Cause Wheel Lock-Up

Wheel lock-up while driving increases the risk of a crash.

#### NHTSA Campaign Number: 25V148000

Manufacturer General Motors, LLC

**Components** POWER TRAIN

#### Potential Number of Units Affected 90,081

#### Summary

General Motors LLC (GM) is recalling certain 2019-2020 Cadillac CT6, 2020-2021 CT4, CT5, and 2020-2022 Chevrolet Camaro vehicles equipped with a 10-speed transmission. The transmission may become damaged internally and cause the front wheels to lock-up.

#### Remedy

Dealers will install transmission control module monitoring software, free of charge. Owner notification letters are expected to be mailed beginning April 21, 2025. Owners may contact Cadillac customer service at 1-800-333-4223 or Chevrolet customer service at 1-800-222-1020. GM's number for this recall is N242480630.

#### Vehicles

MAKE	MODEL	YEAR
CADILLAC	CT4	2020-2021
CADILLAC	CT5	2020-2021
CADILLAC	CT6	2019-2020
CHEVROLET	CAMARO	2020-2022

## Driver's Seat Backrest Malfunction/FMVSS 207, 210

Without a fixate stop bracket, the backrest may fold forward during a crash and increase the risk of injury.

NHTSA Campaign Number: 25V144000

Manufacturer Daimler Coaches North America

**Components** SEATS

#### Potential Number of Units Affected 162

#### Summary

Daimler Coaches North America (Daimler Coaches) is recalling certain 2022-2025 Mercedes Benz Tourrider Business and Premium transits buses. The fixate stop bracket on the driver's seat backrest may not be installed. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 207, "Seating Systems," and 210, "Seat Belt Assembly Anchorages."

#### Remedy

Daimler Coaches will inspect the driver's seat and install a fixate stop as necessary, free of charge. Owner notification letters are expected to be mailed May 1, 2025. Owners may contact Daimler Coaches at 1-416-624-3558. Daimler Coaches number for this recall is 91.10T25237A.

### Vehicles

МАКЕ	MODEL	YEAR
MERCEDES-BENZ	TOURRIDER BUSINESS	2022-2025
MERCEDES-BENZ	TOURRIDER PREMIUM	2022-2025