



Automotive Safety Council

Prevent Protect Notify

NHTSA Recalls of Interest August 27, 2012

Report Date :**August 27, 2012 at 10:15 AM**
NHTSA CAMPAIGN ID Number:**12V409000**

Vehicle Make / Model:

CODA / CODA

Manufacturer: Coda Automotive

NHTSA CAMPAIGN ID Number: 12V409000

Model Year(s):

2012

Mfr's Report Date: AUG 17, 2012

NHTSA Action Number: N/A

Component: AIR BAGS:SIDE/WINDOW

Potential Number of Units Affected: 78

Summary:

CODA Automotive (CODA) is recalling certain model year 2012 CODA vehicles. The side curtain airbags may not have been properly installed which could cause them to not deploy as intended.

Consequence:

In the event of a crash, the side curtain airbags may fail to deploy as intended, increasing the risk of injury.

Remedy:

CODA will notify owners, and dealers will inspect and correct the side curtain airbag installations as needed, free of charge. CODA has not provided a notification schedule. Owners may contact CODA Automotive at 1-855-464-2632.

Report Date :**August 27, 2012 at 10:16 AM**
NHTSA CAMPAIGN ID Number:**12V403000**

Vehicle Make / Model:

INTERNATIONAL / DURASTAR

INTERNATIONAL / PROSTAR

INTERNATIONAL / TRANSTAR

INTERNATIONAL / WORKSTAR

Manufacturer: NAVISTAR, INC

NHTSA CAMPAIGN ID Number: 12V403000

Model Year(s):

2013

2012-2013

2011-2013

2012-2013

Mfr's Report Date: AUG 13, 2012

NHTSA Action Number: N/A

Component: SERVICE BRAKES, AIR:DISC

Potential Number of Units Affected: 943

Summary:

Navistar is recalling certain model year 2011-2013 International vehicles manufactured from November 2, 2010 through May 25, 2012, equipped with Bendix air disc brakes. Bolts that fasten the air disc brake caliper to the caliper mounting plate may not have been tightened to their specified torque. This may cause the mounting bolts to become loose and possibly allow the air disc brake caliper to separate from the caliper mounting plate, resulting in an unexpected pull condition during braking application or an unexpected increase in stopping distance.

Consequence:

An unexpected pull condition during braking application or an unexpected increase in stopping distance, increases the risk of a crash, leading to property damage, personal injury, or death.

Remedy:

Navistar will notify owners, and dealers will replace any missing caliper mounting bolts and tighten caliper mounting bolts, free of charge. The safety recall is expected to begin on October 15, 2012. Owners may contact Navistar at 1-331-332-1590.