



# Automotive Safety Council

Prevent Protect Notify

## NHTSA Recalls of Interest

February 6, 2012

Report Date :February 6, 2012 at 11:53 AM  
NHTSA CAMPAIGN ID Number:12V030000

**Vehicle Make / Model:**

HONDA / ACCORD  
HONDA / CROSSTOUR

**Manufacturer:** HONDA (AMERICAN HONDA MOTOR CO.)

**NHTSA CAMPAIGN ID Number:** 12V030000

**Model Year(s):**

2012  
2012

**Mfr's Report Date:** JAN 31, 2012

**NHTSA Action Number:** N/A

**Component:** AIR BAGS:SIDE/WINDOW

**Potential Number of Units Affected:** 347

**Summary:**

HONDA IS RECALLING CERTAIN MODEL YEAR 2012 ACCORD AND CROSSTOUR VEHICLES. THE DRIVER-SIDE OR PASSENGER-SIDE SIDE CURTAIN AIRBAG INFLATOR MAY NOT HAVE BEEN MANUFACTURED ACCORDING TO CORRECT SPECIFICATIONS.

**Consequence:**

IN THE EVENT OF A CRASH, THE SIDE CURTAIN AIRBAG MAY FAIL TO DEPLOY, INCREASING THE RISK OF INJURY.

**Remedy:**

HONDA WILL REPLACE THE DRIVER'S SIDE OR PASSENGER'S SIDE SIDE CURTAIN AIRBAG AS NEEDED FREE OF CHARGE. THE SAFETY RECALL IS EXPECTED TO BEGIN ON OR ABOUT FEBRUARY 10, 2012. OWNERS MAY CONTACT HONDA CUSTOMER SERVICE AT 1-800-999-1009.

Report Date :February 6, 2012 at 11:54 AM  
NHTSA CAMPAIGN ID Number:12V029000

**Vehicle Make / Model:**

TOYOTA / RAV4

**Manufacturer:** TOYOTA MOTOR NORTH AMERICA, INC.

**NHTSA CAMPAIGN ID Number:** 12V029000

**Model Year(s):**

2011

**Mfr's Report Date:** JAN 31, 2012

**NHTSA Action Number:** N/A

**Component:** AIR BAGS:SIDE/WINDOW

**Potential Number of Units Affected:** 427



APPLICATION.

**Consequence:**

UNEXPECTED CONTINUOUS BRAKE APPLICATION CAN CAUSE THE BRAKES TO OVERHEAT AND LEAD TO A FIRE. UNEXPECTED CONTINUOUS BRAKE APPLICATION CAN CAUSE THE DRIVER TO LOSE CONTROL OF THE VEHICLE, INCREASING THE RISK OF A CRASH. ALSO, THE BRAKES MAY BE APPLIED WITHOUT ILLUMINATING THE BRAKE LIGHTS, FAILING TO GIVE PROPER WARNING TO OTHER DRIVERS.

**Remedy:**

PACCAR WILL NOTIFY OWNERS, AND PROVIDE A TEMPORARY REPAIR UNTIL BENDIX DEVELOPS A PERMANENT REMEDY. THIS SERVICE WILL BE PERFORMED FREE OF CHARGE. THE SAFETY RECALL IS EXPECTED TO BEGIN DURING FEBRUARY 2012. OWNER MAY CONTACT KENWORTH AT 1-425-828-5440 AND PETERBILT AT 1-940-591-4196.