



# Automotive Safety Council

Prevent

Protect

Notify

## NHTSA Recalls of Interest

April 22, 2019

### Insufficient Weld On Head Restraints

**NHTSA Campaign Number:** 19V184000

**Manufacturer** General Motors LLC

**Components** SEATS

**Potential Number of Units Affected** 120

#### **Summary**

General Motors LLC (GM) is recalling certain Chevrolet Equinox and GMC Terrain vehicles. The rear-right seat may have insufficient welds on the head-restraint bracket.

#### **Remedy**

GM will notify owners, and dealers will replace the rear-right seatback frame, free of charge. The recall began April 15, 2019. Owners may contact Chevrolet customer service at 1-800-222-1020 or GMC customer service at 1-800-462-8782. GM's number for this recall is N192209550.

#### **Vehicles**

MAKE	MODEL	YEAR
------	-------	------

CHEVROLET	EQUINOX	2019
-----------	---------	------

GMC	TERRAIN	2019
-----	---------	------

## Driver Warnings May Not Illuminate

**NHTSA Campaign Number:** 19V203000

**Manufacturer** Chrysler (FCA US LLC)

**Components** ELECTRICAL SYSTEM

**Potential Number of Units Affected** 7,929

### **Summary**

Chrysler (FCA US LLC) is recalling certain 2019 Dodge Challenger and Charger and Chrysler 300 vehicles. The instrument cluster may not properly illuminate driver warnings. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 101, "Control and Displays."

### **Remedy**

Chrysler has notified owners, and dealers will update the instrument cluster software, free of charge. The recall began April 8, 2019. Owners may contact Chrysler customer service at 1-800-853-1403. Chrysler's number for this recall is V32.

### **Vehicles**

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
CHRYSLER	300	2019
DODGE	CHALLENGER	2019
DODGE	CHARGER	2019

## Seatbelt Buckle may be Improperly Installed

**NHTSA Campaign Number:** 19V207000

**Manufacturer** Kia Motors America

**Components** SEAT BELTS

**Potential Number of Units Affected** 197

### **Summary**

Kia Motors America (Kia) is recalling certain 2019 Sedona vehicles equipped with an 8-passenger seat arrangement. The seat belt buckle for the second-row middle seat may have been improperly installed on the wrong side of the seat, preventing the proper use of the 3-point seat belt. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 208, "Occupant Crash Protection."

## Remedy

Kia has notified owners, and dealers will inspect the seat belt installation, and reinstall the seat belt buckle to the correct side if necessary, free of charge. The recall began April 8, 2019. Owners may contact Kia customer service at 1-800-333-4542. Kia 's number for this recall is SC177.

## Vehicle

### MAKE MODEL YEAR

KIA SEDONA 2019

## Shifter Cable Bushing May Detach From Transmission

**NHTSA Campaign Number:** 19V293000

**Manufacturer** Chrysler (FCA US LLC)

**Components** POWER TRAIN

**Potential Number of Units Affected** 298,439

## Summary

Chrysler (FCA US LLC) is recalling certain 2013-2016 Dodge Dart vehicles equipped with 6-speed automatic transmissions. The shifter cable bushing may fail allowing the shift cable to detach from the transmission.

## Remedy

Chrysler will notify owners, and dealers will replace the transmission side shifter cable bushing, free of charge. The recall is expected to begin on May 31, 2019. Owners may contact Chrysler customer service at 1-800-853-1403. Chrysler's number for this recall is V34.

## Vehicle

### MAKE MODEL YEAR

DODGE DART 2013-2016

## Side Curtain Air Bags may not Deploy/FMVSS 226

**NHTSA Campaign Number:** 19V296000

**Manufacturer** Karma Automotive LLC

**Components** AIR BAGS

## **Potential Number of Units Affected 231**

### **Summary**

Karma Automotive (Karma) is recalling certain 2018 Karma Revero vehicles. In the event of a roll over crash, the side curtain/head protection air bags may not deploy as intended due to a rollover sensor system that is not enabled. The system also lacks an instrument cluster warning light and a description of the system in the owner's manual. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 226, "Ejection Mitigation."

### **Remedy**

Karma will notify owners, and dealers will replace the existing Airbag Control Unit (ACU) with a rollover enabled ACU and the owners manual will be updated with the description of the system, free of charge. An interim letter notifying owners of the recall will be mailed by April 30, 2019. A second notice will be sent once parts are available. Owners may contact Karma customer service at 1-855-288-6109. Karma's number for this recall is RC-19-84-01.

### **Vehicle**

#### **MAKE MODEL YEAR**

KARMA REVERO 2018