

NHTSA Recalls of Interest December 30, 2019

Inadvertent Air Bag Deployment

NHTSA Campaign Number: 19V885000

Manufacturer Chrysler (FCA US LLC)

Components AIR BAGS, SEAT BELTS

Potential Number of Units Affected 3.329

Summary

Chrysler (FCA US LLC) is recalling certain 2005-2006 Dodge Viper vehicles. The Occupant Restraint Control (ORC) module may inadvertently deploy the air bags and/or seat belt pretensioners.

Remedy

Chrysler will notify owners, and dealers will replace the ORC module, free of charge. The recall is expected to begin January 31, 2020. Owners may contact Chrysler customer service at 1-800-853-1403. Chrysler's number for this recall is VE4.

Vehicle

MAKE MODEL YEAR

DODGE VIPER 2005-2006

Rearview Image Can Remain on Radio Display

NHTSA Campaign Number: 19V886000

Manufacturer Chrysler (FCA US LLC)

Components EQUIPMENT, BACK OVER PREVENTION

Potential Number of Units Affected 20,441

Summary

Chrysler (FCA US LLC) is recalling certain 2018-2019 Pacifica vehicles equipped with an 8.4 inch radio display, 360 degree surround view camera system, and seat back video screens. A software error can cause the rearview camera image to remain displayed on the radio after the vehicle has been shifted out of reverse. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 111, "Rearview Mirrors."

Remedy

Chrysler will notify owners, and dealers will update the radio software, free of charge. The recall is expected to begin January 31, 2020. Owners may contact Chrysler customer service at 1-800-853-1403. Chrysler's number for this recall is VE2.

Vehicle

MAKE MODEL YEAR

CHRYSLER PACIFICA 2018-2019

Incorrect TPMS Installed/FMVSS 138

NHTSA Campaign Number: 19V887000

Manufacturer Chrysler (FCA US LLC)

Components TIRES

Potential Number of Units Affected 34

Summary

Chrysler (FCA US LLC) is recalling certain 2019 Ram 1500 trucks. An incorrect Tire Pressure Monitoring System (TPMS) sensor could have been installed during production causing the sensor to not display the low tire pressure warning indicator. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 138, "Tire Pressure Monitoring Systems."

Remedy

Chrysler will notify owners, and dealers will replace the TPMS sensor, free of charge. The recall is expected to begin January 31, 2020. Owners may contact Chrysler customer service at 1-800-853-1403. Chrysler's number for this recall is VE1.

Vehicle

MAKE MODEL YEAR

RAM 1500 2019