

NHTSA Recalls of Interest January 4, 2021

Parking Brake May Release Unexpectedly/FMVSS 121

NHTSA Campaign Number: 20V787000

Manufacturer Daimler Trucks North America, LLC

Components SERVICE BRAKES, AIR, PARKING BRAKE

Potential Number of Units Affected 28

Summary

Daimler Trucks North America, LLC (DTNA) is recalling certain 2021 Thomas Built Saf-T-Liner C2 Jouley electric school buses. If the service brake pedal is pressed and then released while the parking brake is engaged, the parking brake may release unexpectedly. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 121, "Air Brake Systems."

Remedy

DTNA will notify owners, and dealers will update the electronic control unit (ECU) software, free of charge. The recall is expected to begin February 13, 2021. Owners may contact DTNA customer service at 1-800-745-8000. DTNA's number for this recall is FL-870.

Vehicle

MAKE MODEL YEAR

THOMAS BUILT BUSES SAF-T-LINER C2 2021

Brake Caliper May Leak

NHTSA Campaign Number: 20V802000

Manufacturer Daimler Vans USA, LLC

Components SERVICE BRAKES, HYDRAULIC

Potential Number of Units Affected 9,094

Summary

Daimler Vans USA, LLC (DVUSA) is recalling certain 2019-2020 Mercedes-Benz Sprinter and Freightliner Sprinter vehicles equipped with electric parking brakes. The rear brake calipers may leak brake fluid into the housing of the electric parking brake connected to the rear axle service brake system, allowing air to enter the hydraulic brake system.

Remedy

DVUSA has not yet established a remedy. The recall is expected to begin January 25, 2021. Owners may contact DVUSA customer service at 1-877-762-8267. DVUSA's number for this recall is VS3BREPB.

Vehicles

| MAKE | MODEL | YEAR |
|----------------------------|--------------------------------|-----------|
| FREIGHTLINER | SPRINTER 1500 | 2010 2020 |
| FREIGHTLINER | SPRINTER 1500 SPRINTER 2500 | |
| | SPRINTER 2500 SPRINTER 3500 | |
| FREIGHTLINER EDELCHTLINER | SPRINTER 3500 SPRINTER 4500 | |
| FREIGHTLINER MERCEDES-BENZ | | |
| | | |
| MERCEDES-BENZ | | |
| MERCEDES-BENZ | | |
| MERCEDES-BENZ | SPKINTER 4500 | 2019-2020 |

Front Left Brake Caliper May Fracture

NHTSA Campaign Number: 20V808000

Manufacturer General Motors, LLC

Components SERVICE BRAKES, HYDRAULIC

Potential Number of Units Affected 464

Summary

General Motors, LLC (GM) is recalling certain 2020 Chevrolet Bolt EV vehicles. These vehicles may have an improperly cast front left brake caliper that can fracture during a high-pressure braking event.

Remedy

GM will notify owners, and dealers will inspect the casting lot number on the front left brake caliper and replace it if necessary, free of charge. The recall is expected to begin February 5, 2021. Owners may contact Chevrolet customer service at 1-800-222-1020. GM's number for this recall is N202321400.

Vehicle

MAKE MODEL YEAR

CHEVROLET BOLT EV 2020

Incorrect Bolts Used to Attach Seat Belts

NHTSA Campaign Number: 20V811000

Manufacturer General Motors, LLC

Components SEAT BELTS

Potential Number of Units Affected 470

Summary

General Motors, LLC (GM) is recalling certain 2020 Chevrolet Bolt EV and 2021 GMC Canyon and Sierra 1500, 2500 and 3500, Yukon, Yukon XL, Cadillac Escalade and Escalade ESV and Chevrolet Blazer, Camaro, Colorado, Equinox, Silverado 1500, 2500 and 3500, Suburban and Tahoe vehicles. Incorrect bolts may have been used at one or more fastening locations to secure the seat belts to the vehicle. If an incorrect bolt was used, the seat belt may not be properly attached to the vehicle.

Remedy

GM will notify owners, and dealers will replace the suspect bolts, free of charge. The recall is expected to begin February 6, 2021. Owners may contact GMC customer service at 1-800-462-8785, Cadillac customer service at 1-800-458-8006, or Chevrolet customer service at 1-800-222-1020. GM's number for this recall is N202322230.

Vehicles

| MAKE | MODEL | YEAR |
|----------|--------------|------|
| CADILLAC | ESCALADE | 2021 |
| CADILLAC | ESCALADE ESV | 2021 |

| MAKE | MODEL | YEAR |
|-----------|----------------|------|
| CHEVROLET | BLAZER | 2021 |
| CHEVROLET | BOLT EV | 2020 |
| CHEVROLET | CAMARO | 2021 |
| CHEVROLET | COLORADO | 2021 |
| CHEVROLET | EQUINOX | 2021 |
| CHEVROLET | SILVERADO 1500 | 2021 |
| CHEVROLET | SILVERADO 2500 | 2021 |
| CHEVROLET | SILVERADO 3500 | 2021 |
| CHEVROLET | SUBURBAN | 2021 |
| CHEVROLET | TAHOE | 2021 |
| GMC | CANYON | 2021 |
| GMC | SIERRA 1500 | 2021 |
| GMC | SIERRA 2500 | 2021 |
| GMC | SIERRA 3500 | 2021 |
| GMC | YUKON | 2021 |
| GMC | YUKON XL | 2021 |