



Automotive Safety Council

Prevent

Protect

Notify

NHTSA Recalls of Interest July 19, 2021

Front Driver's Side Air Bag Missing Metal Tabs

NHTSA Campaign Number: 21V495000

Manufacturer General Motors, LLC

Components AIR BAGS

Potential Number of Units Affected 12

Summary

General Motors, LLC. (GM) is recalling certain 2021 Chevrolet Silverado 1500 vehicles. The front driver's side air bag module may be missing one or more metal tabs that secure the plastic air bag cover to the housing.

Remedy

Dealers will inspect the driver frontal air bag, and replace it if necessary, free of charge. Owner notification letters are expected to be mailed August 16, 2021. Owners may contact Chevrolet customer service at 1-800-222-1020. GM's number for this recall is N212336560.

Vehicle

MAKE	MODEL	YEAR
------	-------	------

CHEVROLET	SILVERADO 1500	2021
-----------	----------------	------

Side Impact Crash Sensor Connectors May Loosen

NHTSA Campaign Number: 21V527000

Manufacturer Mercedes-Benz USA, LLC

Components AIR BAGS

Potential Number of Units Affected 542

Summary

Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2021 CLS450, AMG E53, AMG CLS53, E350, E450, AMG GT43, AMG GT53, 2020 S450, S560, G550, AMG GLC63, 2020-2021 GLC300, and AMG G63 vehicles. The side crash sensor connectors may come loose, which could delay the activation of air bags and seatbelts during a side impact crash.

Remedy

Dealers will inspect and replace as necessary, the side impact crash sensors, free of charge. Owner notification letters are expected to be mailed September 10, 2021. Owners may contact MBUSA customer service at 1-800-367-6372.

Vehicles

MAKE	MODEL	YEAR
MERCEDES-BENZ	AMG CLS53	2021
MERCEDES-BENZ	AMG E53	2021
MERCEDES-BENZ	AMG G63	2020-2021
MERCEDES-BENZ	AMG GLC63	2020
MERCEDES-BENZ	AMG GT43	2021
MERCEDES-BENZ	AMG GT53	2021
MERCEDES-BENZ	CLS450	2021
MERCEDES-BENZ	E350	2021
MERCEDES-BENZ	E450	2021
MERCEDES-BENZ	G550	2020
MERCEDES-BENZ	GLC300	2020-2021
MERCEDES-BENZ	S450	2020
MERCEDES-BENZ	S560	2020

Instrument Panel Interference with Air Bag

NHTSA Campaign Number: 21V500000

Manufacturer Jaguar Land Rover North America, LLC

Components AIR BAGS

Potential Number of Units Affected 1

Summary

Jaguar Land Rover North America, LLC (Jaguar) is recalling one 2018 F-Type vehicle. A portion of the instrument panel may interfere with the front passenger air bag during deployment, possibly tearing the air bag cushion.

Remedy

A dealer will replace the instrument panel facia, free of charge. The owner notification letter is expected to be mailed August 27, 2021. Owners may contact Jaguar customer service at 1-800-452-4827. Jaguar's number for this recall is H365.

Vehicle

MAKE MODEL YEAR

JAGUAR F-TYPE 2018

Deformed Front Seat Track Bracket

NHTSA Campaign Number: 21V499000

Manufacturer Jaguar Land Rover North America, LLC

Components SEATS

Potential Number of Units Affected 603

Summary

Jaguar Land Rover North America, LLC (Land Rover) is recalling certain 2021 Defender vehicles equipped with manually-adjustable front seats. The front seat track end-stop bracket may become deformed, which could prevent the seat from locking into place.

Remedy

Dealers will replace the front seat tracks, free of charge. Owner notification letters are expected to be mailed August 27, 2021. Owners may contact Land Rover customer service at 1-800-637-6837. Land Rover's number for this recall is N609.

Vehicle

MAKE MODEL YEAR

LAND ROVER DEFENDER 2021

Liftgate Hinges Can Separate/FMVSS 206

NHTSA Campaign Number: 21V525000

Manufacturer Nissan North America, Inc.

Components STRUCTURE

Potential Number of Units Affected 13,215

Summary

Nissan North America, Inc. (Nissan) is recalling certain 2021 Rogue Sport vehicles. The liftgate hinges can separate from the vehicle during a rear end crash. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 206, "Door Locks and Door Retention Components."

Remedy

Dealers will replace the left and right liftgate hinges, free of charge. Owner notification letters are expected to be mailed September 7, 2021. Owners may contact Nissan customer service at 1-800-867-7669. Nissan's number for this recall is R21A7.

Vehicle

MAKE MODEL YEAR

NISSAN ROGUE SPORT 2021

Excessive Voltage at Second-Row Power Outlet

NHTSA Campaign Number: 21V526000

Manufacturer Mercedes-Benz USA, LLC

Components ELECTRICAL SYSTEM

Potential Number of Units Affected 1,690

Summary

Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2020 GLB 250 vehicles. The accessory power outlet for the second-row seating may have excessive voltage due to an incorrect voltage converter socket.

Remedy

Dealers will inspect and replace the voltage converter, as necessary, free of charge. Owner notification letters are expected to be mailed September 3, 2021. Owners may contact MBUSA customer service at 1-800-367-6372.

Vehicle

MAKE MODEL YEAR

MERCEDES-BENZ GLB250 2020

