



Automotive Safety Council

Prevent

Protect

Notify

NHTSA Recalls of Interest

May 13, 2024

Braking May Require Increased Force

Extended stopping distance can increase the risk of a crash.

NHTSA Campaign Number: 24V316000

Manufacturer Daimler Vans USA, LLC

Components ELECTRONIC STABILITY CONTROL (ESC)

Potential Number of Units Affected 184

Summary

Daimler Vans USA, LLC (DVUSA) is recalling certain 2024 Mercedes-Benz eSprinter vehicles. Due to a software error in the electronic stability program (ESP), the force required to stop the vehicle may increase, possibly requiring an extended distance to stop.

Remedy

Dealers will update the ESP control unit software, free of charge. Owner notification letters are expected to be mailed July 1, 2024. Owners may contact DVUSA customer service at 1-877-762-8267. DVUSA's number for this recall is VS3EBOOSTF.

Vehicle

MAKE	MODEL	YEAR
MERCEDES-BENZ	ESPRINTER	2024

Seat Belt Warning System Malfunction/FMVSS 208

A malfunctioning seat belt warning system can result in improper seat belt use, increasing the risk of injury in a crash.

NHTSA Campaign Number: 24V312000

Manufacturer Jayco, Inc.

Components SEAT BELTS

Potential Number of Units Affected 33

Summary

Jayco, Inc. (Jayco) is recalling certain Jayco Swift, Swift LI, Entegra Coach Ethos, and Ethos LI motorhomes. The driver seat belt warning light and audible chime may not activate as intended. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 208, "Occupant Crash Protection."

Remedy

FCA dealers will inspect and replace the driver seat belt buckle as necessary, free of charge. Owner notification letters are expected to be mailed June 14, 2024. Owners may contact Jayco customer service at 1-800-283-8267.

Vehicles

MAKE	MODEL	YEAR
ENTEGRRA	ETHOS	2023
ENTEGRRA	ETHOS LI	2023
JAYCO	SWIFT	2023
JAYCO	SWIFT LI	2023
