



Automotive Safety Council

Prevent

Protect

Notify

NHTSA Recalls of Interest

May 27, 2024

Air Bags May Not Deploy as Intended/FMVSS 208

Front air bags that do not deploy as intended can increase the risk of injury in a crash.

NHTSA Campaign Number: 24V346000

Manufacturer Chrysler (FCA US, LLC)

Components AIR BAGS, STRUCTURE

Potential Number of Units Affected 7

Summary

Chrysler (FCA US, LLC) is recalling certain 2024 Jeep Grand Cherokee vehicles. The front bumper may be missing energy absorbing foam, which can cause the front air bags not to deploy as intended. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 208, "Occupant Crash Protection."

Remedy

Dealers will inspect the vehicles and install the foam as necessary, free of charge. Owner notification letters are expected to be mailed July 5, 2024. Owners may contact FCA US, LLC customer service at 1-800-853-1403. FCA US, LLC's number for this recall is 41B.

Vehicle

MAKE	MODEL	YEAR
JEEP	GRAND CHEROKEE	2024

Instrument Panel Display Malfunction/FMVSS 101

Displays that do not show critical information, such as vehicle speed or the rearview camera image, increase the risk of a crash.

NHTSA Campaign Number: 24V344000

Manufacturer Volkswagen Group of America, Inc.

Components BACK OVER PREVENTION, EQUIPMENT, ELECTRICAL SYSTEM

Potential Number of Units Affected 79,953

Summary

Volkswagen Group of America, Inc. (VW) is recalling certain 2021-2023 ID.4 vehicles. Due to a software issue, affected vehicles may experience center displays and instrument panel displays that do not boot, or that sporadically reset. This can result in loss of speedometer information or loss of rearview camera image. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard numbers 101, "Control and Displays" and 111, "Rear Visibility."

Remedy

Dealers will update the vehicle software, free of charge. Owner notification letters are expected to be mailed July 12, 2024. Owners may contact VW customer service at 1-800-893-5298. VW's number for this recall is 919A.

Vehicle

MAKE	MODEL	YEAR
VOLKSWAGEN	ID.4	2021-2023

Brakes May Activate Unexpectedly

Unexpected braking increases the risk of a crash.

NHTSA Campaign Number: 24V349000

Manufacturer Mazda North American Operations

Components FORWARD COLLISION AVOIDANCE

Potential Number of Units Affected 9,914

Summary

Mazda North American Operations (Mazda) is recalling certain 2024 CX-90 vehicles. The brakes may activate suddenly due to the automatic braking system falsely detecting certain objects while driving.

Remedy

Dealers will reprogram the vehicle control module (VCM) with updated software, free of charge. Owner notification letters are expected to be mailed July 17, 2024. Owners may contact Mazda customer service at 1-800-222-5500 Option 6. Mazda's number for this recall is 6724E.

Vehicle

MAKE	MODEL	YEAR
MAZDA	CX-90	2024

High Voltage Battery Safety Plug May Overheat

A loss of drive power increases the risk of a crash, and a fire increases the risk of injury.

NHTSA Campaign Number: 24V358000

Manufacturer Kia America, Inc.

Components ELECTRICAL SYSTEM

Potential Number of Units Affected 2,209

Summary

Kia America, Inc. (Kia) is recalling certain 2022 Niro EV vehicles. The high voltage battery safety plug may overheat and melt, which can cause a loss of drive power or fire.

Remedy

Owners are advised not to charge their vehicle in a garage or any other covered structure until the recall repair is completed. Dealers will replace the safety plug, free of charge. Owner notification letters are expected to be mailed July 19, 2024. Kia's number for this recall is SC314.

Notes

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.

1 Affected Product

Vehicle

MAKE	MODEL	YEAR
KIA	NIRO EV	2022

Hood May Open While Driving

A hood that opens while driving can detach and become a road hazard, or obstruct the driver's view, increasing the risk of a crash.

NHTSA Campaign Number: 24V348000

Manufacturer Lamborghini (Automobili Lamborghini)

Components LATCHES/LOCKS/LINKAGES

Potential Number of Units Affected 2,133

Summary

Lamborghini (Automobili Lamborghini) is recalling certain 2023-2024 Urus Performante and Urus S vehicles. The hood latch striker may separate and fail, resulting in an unlatched hood that can open or detach while driving.

Remedy

Dealers will inspect and repair the hood, and install a striker support plate if necessary, free of charge. Owner notification letters are expected to be mailed June 28, 2024. Owners may contact Lamborghini customer service at 1-866-681-6276. Lamborghini's number for this recall is L636-R.02.24.

Vehicle

MAKE	MODEL	YEAR
LAMBORGHINI	URUS	2023-2024
