



Automotive Safety Council

Prevent

Protect

Notify

NHTSA Recalls of Interest

January 13, 2025

Unexpected Vehicle Movement/FMVSS 114

When the vehicle is not in "Park" and the ignition is shut off, the vehicle could move unexpectedly, increasing the risk of a vehicle rollaway and crash.

NHTSA Campaign Number: 24V969000

Manufacturer Nissan North America, Inc.

Components ELECTRICAL SYSTEM

Potential Number of Units Affected 20

Summary

Nissan North America, Inc. (Nissan) is recalling certain 2025 Kicks vehicles. The "Shift-to-Park" warning may not activate as intended when the vehicle is shut off and still in a gear other than "Park." As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 114, "Theft Protection and Rollaway Prevention."

Remedy

Dealers will reconfigure the body control module (BCM) to activate the "Shift-to-Park" warning, free of charge. Owner notification letters are expected to be mailed January 29, 2025. Owners may contact Nissan customer service at 1-800-867-7669. Nissan's number for this recall is PMA42.

Vehicle

MAKE	MODEL	YEAR
NISSAN	KICKS	2025

Rearview Camera Image May Fail/FMVSS 111

A rearview camera that does not display an image reduces the driver's rear view, increasing the risk of a crash.

NHTSA Campaign Number: 25V002000

Manufacturer Tesla, Inc.

Components BACK OVER PREVENTION, ELECTRICAL SYSTEM

Potential Number of Units Affected 239,382

Summary

Tesla, Inc. (Tesla) is recalling certain 2024-2025 Model 3, Model S, 2023-2025 Model X, and 2023-2025 Model Y vehicles. The computer circuit board may short, resulting in the loss of the rearview camera image. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 111, "Rear Visibility."

Remedy

Tesla released an over-the-air (OTA) software update, free of charge. Tesla will also identify any vehicles that experienced a circuit board failure, or stress that may lead to a circuit board failure, and replace the affected computers, free of charge. Owner notification letters are expected to be mailed March 7, 2025. Owners may contact Tesla customer service at 1-877-798-3752. Tesla's number for this recall is SB-25-00-001.

Vehicles

MAKE	MODEL	YEAR
TESLA	MODEL 3	2024-2025
TESLA	MODEL S	2024-2025
TESLA	MODEL X	2023-2025
TESLA	MODEL Y	2023-2025

Obstructed Rearview Camera Image/FMVSS 111

An obstructed rearview camera image can reduce the driver's rear visibility, increasing the risk of a crash or injury.

NHTSA Campaign Number: 25V001000

Manufacturer Aston Martin The Americas

Components BACK OVER PREVENTION

Potential Number of Units Affected 1,452

Summary

Aston Martin The Americas (Aston Martin) is recalling certain 2024-2025 DB12, 2025 Vantage, and 2025 DBX707 vehicles. The rearview camera image may be obstructed by the infotainment home screen menu when the vehicle is placed in reverse. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 111, "Rear Visibility."

Remedy

The head unit software will be updated by a dealer or through an over-the-air (OTA) update, free of charge. Owner notification letters are expected to be mailed January 20, 2025. Owners may contact Aston Martin customer service at 1-888-923-9988. Aston Martin's number for this recall is RA-30-2015.

Vehicles

MAKE	MODEL	YEAR
ASTON MARTIN	DB12	2024-2025
ASTON MARTIN	DBX707	2025
ASTON MARTIN	VANTAGE	2025