



# Automotive Safety Council

Prevent

Protect

Notify

## NHTSA Recalls of Interest

April 14, 2025

### Occupant Classification may Turn Off Air Bag

An air bag that fails to deploy during a crash increases the risk of injury.

**NHTSA Campaign Number:** 25V221000

**Manufacturer** Porsche Cars North America, Inc.

**Components** AIR BAGS

**Potential Number of Units Affected** 9,735

#### Summary

Porsche Cars North America, Inc. (Porsche) is recalling certain 2022-2023 Taycan vehicles. An occupant classification system error may deactivate the front passenger air bag.

#### Remedy

Dealers will replace the front passenger seat cushion, free of charge. Owner notification letters are expected to be mailed June 6, 2025. Owners may contact Porsche customer service at 1-800-767-7243. Porsche's number for this recall is ASA2.

#### Vehicle

MAKE	MODEL	YEAR
PORSCHE	TAYCAN	2022-2023

## Rearview Camera May Show Blurry Image/FMVSS111

A blurry rearview image can reduce the driver's view of what is behind the vehicle, increasing the risk of a crash.

**NHTSA Campaign Number:** 25V225000

**Manufacturer** Volkswagen Group of America, Inc.

**Components** BACK OVER PREVENTION

**Potential Number of Units Affected** 313

### Summary

Volkswagen Group of America, Inc. (Audi) is recalling certain 2025 SQ6 e-tron and Q6 e-tron vehicles. The rearview camera may show a blurry image. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 111, "Rear Visibility."

### Remedy

Dealers will replace the rearview camera. In addition, dealers will inspect and replace surround view cameras as necessary. All repairs will be performed free of charge. Owner notification letters are expected to be mailed June 6, 2025. Owners may contact Audi customer service at 1-800-253-2834. Audi's number for this recall is 90XM.

### Vehicles

---

MAKE	MODEL	YEAR
AUDI	Q6 E-TRON	2025
AUDI	SQ6 E-TRON	2025

---

## Rearview Camera Image May Not Display/FMVSS 111

A rearview camera that does not display an image decreases the driver's visibility, increasing the risk of a crash.

**NHTSA Campaign Number:** 25V220000

**Manufacturer** Porsche Cars North America, Inc.

**Components** BACK OVER PREVENTION

**Potential Number of Units Affected** 8,571

### Summary

Porsche Cars North America, Inc. (Porsche) is recalling certain 2024-2025 Macan Electric vehicles. The rearview camera may show a blurry image or fail to display. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 111, "Rear Visibility."

## Remedy

Dealers will update the control unit software, inspect, and replace the rearview camera as necessary, free of charge. Owner notification letters are expected to be mailed June 6, 2025. Owners may contact Porsche customer service at 1-800-767-7243. Porsche's number for this recall is ASA3.

## Vehicle

---

MAKE	MODEL	YEAR
PORSCHE	MACAN ELECTRIC	2024-2025

---

## Headlights May Flicker or Shut Off

Loss of headlight illumination can reduce visibility, increasing the risk of a crash or injury.

**NHTSA Campaign Number:** 25V210000

**Manufacturer** Honda (American Honda Motor Co.)

**Components** EXTERIOR LIGHTING

**Potential Number of Units Affected** 7,212

### Summary

Honda (American Honda Motor Co.) is recalling certain 2018-2025 CB300R motorcycles. The headlights may flicker or shut off while driving.

### Remedy

Dealers will replace the headlight assembly, free of charge. Owner notification letters are expected to be mailed May 30, 2025. Owners may contact Honda's customer service at 866-784-1870. Honda's number for this recall is KS0.

## Vehicle

---

MAKE	MODEL	YEAR
HONDA	CB300R	2018-2025

---

## Hazard Switch Back Lighting May Fail/FMVSS 101

A hazard switch that is not illuminated may be difficult to locate when needed, increasing the risk of a crash or injury.

**NHTSA Campaign Number:** 25V214000

**Manufacturer** Volvo Trucks North America

**Components** INTERIOR LIGHTING, EXTERIOR LIGHTING

**Potential Number of Units Affected** 5,257

### Summary

Volvo Trucks North America (Volvo Trucks) is recalling certain 2023-2026 New VN trucks. The hazard switch back lighting may become inoperative. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 101, "Controls and Displays."

### Remedy

Dealers will update the vehicle master control unit (VMCU) software, free of charge. Owner notification letters are expected to be mailed June 1, 2025. Owners may contact Volvo Trucks' customer service at 800-528-6586. Volvo Trucks' number for this recall is RVXX2503.

### Vehicle

---

MAKE	MODEL	YEAR
VOLVO	NEW VN	2023-2026

---

## Instrument Panel Display Failure

An instrument panel display that fails to show critical safety information, such as the speedometer or warning lights, increases the risk of a crash.

**NHTSA Campaign Number:** 25V201000

**Manufacturer** Volkswagen Group of America, Inc.

**Components** ELECTRICAL SYSTEM

**Potential Number of Units Affected** 44,387

### Summary

Volkswagen Group of America, Inc. (Audi) is recalling certain 2021 SQ8, A6 SEDAN, A7, A8, Q7, Q8, RS6 Avant, RS7, RSQ8, S6 SEDAN, S7, S8, A6 Allroad, and SQ7 vehicles. Due to a software error, the instrument panel display may fail.

### Remedy

Dealers will update the instrument panel module software, free of charge. Owner notification letters are expected to be mailed May 30, 2025. Owners may contact Audi customer service at 1-800-253-2834. Audi's number for this recall is 90VC.

### Notes

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 888-327-4236 (TTY 888-275-9171) or go to [nhtsa.gov](https://www.nhtsa.gov)

# Vehicles

---

MAKE	MODEL	YEAR
AUDI	A6	2021
AUDI	A6 ALLROAD	2021
AUDI	A7	2021
AUDI	A8	2021
AUDI	Q7	2021
AUDI	Q8	2021
AUDI	RS 6 AVANT	2021
AUDI	RS 7	2021
AUDI	RS Q8	2021
AUDI	S6	2021
AUDI	S7	2021
AUDI	S8	2021
AUDI	SQ7	2021
AUDI	SQ8	2021

