

NHTSA Recalls of Interest September 9, 2024

Disabled Electronic Stability Control/FMVSS 126

Driving with a disabled electronic stability control system can increase the risk of a crash.

NHTSA Campaign Number: 24V653000

Manufacturer Chrysler (FCA US, LLC)

Components SERVICE BRAKES, HYDRAULIC, ELECTRONIC STABILITY CONTROL (ESC)

Potential Number of Units Affected 1,227,808

Summary

Chrysler (FCA US, LLC) is recalling certain 2019, 2021-2024 Ram 1500 vehicles. Due to a software malfunction, the anti-lock brake system (ABS) control module may disable the electronic stability control system. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 126, "Electronic Stability Control Systems."

Remedy

Dealers will update the ABS control module software, free of charge. Owner notification letters are expected to be mailed October 3, 2024. Owners may contact FCA US, LLC customer service at 1-800-853-1403. FCA US, LLC's number for this recall is 85B.

Vehicle

MAKE	MODEL	YEAR
RAM	1500	2019, 2021-2024

Instrument Panel Failure/FMVSS 101

An instrument panel that fails to display critical safety information, such as the speedometer or warning lights, can increase the risk of a crash.

NHTSA Campaign Number: 24V652000

Manufacturer Chrysler (FCA US, LLC)

Components ELECTRICAL SYSTEM

Potential Number of Units Affected 32,863

Summary

Chrysler (FCA US, LLC) is recalling certain 2020-2024 Jeep Gladiator and 2018-2024 Jeep Wrangler vehicles. The instrument panel cluster may experience an internal short circuit and fail. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 101, "Controls and Displays."

Remedy

Dealers will replace the instrument panel cluster, free of charge. Owner notification letters are expected to be mailed October 3, 2024. Owners may contact FCA customer service at 1-800-853-1403. FCA's number for this recall is 30B.

Vehicles

MAKE	MODEL	YEAR
JEEP	GLADIATOR	2020-2024
JEEP	WRANGLER	2018-2024

Seat Belt Not Retracting Properly/FMVSS 209

A seat belt that does not retract properly may result in a loose seat belt, which can increase the risk of injury in a crash.

NHTSA Campaign Number: 24V647000

Manufacturer Nova Bus (US) Inc.

Components SEAT BELTS

Potential Number of Units Affected 1,575

Summary

Nova Bus (US) Inc. (Nova) is recalling certain 2010-2020 LFS Artic and 2012-2024 LFS vehicles. The driver's seat belt may not retract properly. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 209, "Seat Belt Assemblies."

Remedy

The remedy is currently under development. Owner notification letters are expected to be mailed November 02, 2024. Owners may contact Nova customer service at 1-800-350-6682. Nova's number for this recall is CR5635. This recall expands and replaces previous recall number 23V-350. Vehicles that were previously recalled under 23V-350 will need to have the new remedy completed.

Vehicles

MAKE	MODEL	YEAR
NOVA BUS	LFS	2012-2024
NOVA BUS	LFS ARTIC	2010-2020

Rearview Camera Image May Not Display/FMVSS 111

A rearview camera image that does not display decreases the driver's visibility, increasing the risk of a crash.

NHTSA Campaign Number: 24V641000

Manufacturer Jayco, Inc.

Components BACK OVER PREVENTION

Potential Number of Units Affected 1,245

Summary

Jayco Inc. (Jayco) is recalling certain 2023-2025 Entegra Ethos, Ethos LI, Arc, Jayco Swift, Swift LI, and Comet motorhomes. The radio software may prevent the rearview image from displaying. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 111, "Rear Visibility."

Remedy

The radio software will be updated through an over-the-air (OTA) update or by a dealer, free of charge. Owner notification letters are expected to be mailed September 27, 2024. Owners may contact Jayco customer service at 1-800-283-8267 or FCA customer service at 1-800-853-1403. Jayco's number for this recall is FCA 24V-436.

Vehicles

MAKE	MODEL	YEAR
ENTEGRA	ARC	2023-2025
ENTEGRA	ETHOS	2023-2025
ENTEGRA	ETHOS LI	2023-2025
JAYCO	COMET	2023-2025
JAYCO	SWIFT	2023-2025
JAYCO	SWIFT LI	2023-2025

Improperly Secured Passenger Air Bag Inflator

An improperly secured air bag inflator may not deploy as intended, increasing the risk of injury during a crash.

NHTSA Campaign Number: 24V643000

Manufacturer Volkswagen Group of America, Inc.

Components AIR BAGS

Potential Number of Units Affected 837

Summary

Volkswagen Group of America, Inc. (VW) is recalling certain 2023-2024 ID4 vehicles. The fasteners securing the passenger frontal air bag inflator may be loose.

Remedy

Dealers will inspect and replace the air bag as necessary, free of charge. Owner notification letters are expected to be mailed October

18, 2024. Owners may contact Volkswagen customer service at 1-800-893-5298. Volkswagen's number for this recall is 69E8.

Vehicle

MAKE	MODEL	YEAR
VOLKSWAGEN	ID.4	2023-2024